Saint Mark UMC

Endurability Committee Framework and Roadmap

Community Engagement – December 2022

Survey Results



Prioritization for Saint Mark Facility Investments

https://www.stmarkumc.org/building-updates


The Endurability Committee is approaching the end of their studies and project recommendations for Saint Mark. The Endurability Committee was originally charged with developing a plan to ensure our buildings are watertight, to repair water damage to interiors, to connect our 2nd floor to the new parking deck, and to upgrade infrastructure as necessary.

We will kick off 2023 with active community engagement and educational sessions in January and February. The work of the Endurability Committee has created a multi-year facilities improvement roadmap which will be managed and executed as funding is available – a significant portion of which is in-hand from our property sale.

The schedule below outlines the community engagement process for the next few months:

December 2022 January 2023 February – April 2023 March – May 2023 • Share Phase 0 Communications. Celebrate Announce rededication of the survey results / education, priorities for next details community Chapel phase outreach focused Share Phase 1 and Funding strategy on next phase Phase 2 project developed for next prioritization details phases Page 2

Prioritization for Saint Mark Facility Investments



In 2021, an invitation to complete a facility survey was provided to the community.

The Church Council and Endurability Committee have reviewed and compared the 2021 community survey results with consulting guidance received as part of the Endurability Committee's work. There are many intersections, and all community input will have a place in the facility roadmap.

The following pages provide a thematic summary of the Phase 0 Community Survey. Appendix A includes details of all comments to be sure no contributing thoughts are lost in this process. With the completion of Phases 1 and 2, we will be making decisions on Phase 3 and future phase prioritization and funding needs. The Church Council reviewed a full study compilation and recommendations from the Endurability Committee in December, and you will receive notifications for opportunities to engage in conversations with the Church Council and Endurability Committee members starting in January. We hope the following pages will be helpful by providing an understanding of the thoughts of the community.

2021 Endurability Committee Survey

Survey Participants = 82

Estimate: Invited to Participate = ~1200

% of Participation = \sim 6.9%

Demographics:

- Ages = not known
- Gender = not known
- Average Years at Saint Mark = 16.7 years

Categories of Comments

Risk and Deferred Modernization Maintenance Regular **Great Ideas** Maintenance

Saint Mark 2021 Survey / Q3-2022 Facility Master Plan Project List

Completed or In Process Projects

Captured in Q3-2022 Master Plan Project Inventory List, subject to revisions

Requires electrical / plumbing infrastructure investment to enable

Continual improvements from operating funds or donor gifts, as available many continual improvements from operating funds or donor gifts, as available

			reequires en	petricur / pra	Inonig initusti	actare mives		1 1	1	010		ı			1	016		
				0.4		0.6	07		0.0	Q10 -			012	014	015	Q16 -		010
	Q1 -	Q2 - Open	Q3 -	Q4		Q6	Q7 - Area		Q9 -	Parlor /			Q13 -	Q14 -	Q15 -	Education	~	Q18 -
	Overall	Air	Courtyard	Exterior	Q5 Exterior	Sanctuary	Below	Q8 - Wade	Chapel	Brides	Q11 - New	-	Gymnasiu	Education	Education	Bldg -	Q17	Other
	Exteriror	Breezeway	Playground	Lighting	Landscaping	Interior	Sanctuary	Hall	Interior	Room	Bridge	Restrooms	m	Bldgs	Bldg	Floor 1	Basement	Areas
Major Repairs / Deferred Maintenan	5	-	-	-	-	82	34	-	12	10	-	43	11	14	18	6	10	14
Bathroom - Upgrade							28			5		35		5	3			ł
Electrical & Plumbing - Upgrade	1									1		8		2	5	2	1	3
(Enables other projects)																		
Improve Water Dispensers							1											1
HVAC Improvements										1			3	3	6	1		1
Repairs:																		
Repair Damaged Areas							3											1
Plaster Repair						42			8									i
Roof Leaks - Repair	1								4				7					3
Solve Water Issues																		1
Window Repairs / Replacement	1					39				3				4	4	2		2
Waterseal Downstair Areas	-					57				J				·				1
Wiggins House - Bring Up to Code																	2	
Remove Drop Ceiling							t						1					
Elevator Addition / Replacement							2										6	2
Doors - Repair / Restore	2					1										1	1	i
Major Upgrades / Renovations	8	33	20	-	8	2	13	32	_	5	31	17	8	9	7	4	10	5
Major Renovation	2	19	20		8	2	12	15		5	01	17	6	7	3	4	3	2
Kitchen - Update Wade Hall Kitchen		17	20		0		12	17		3		1,	U	,	3			3
Kitchen - Youth - Update Kitchen								1 /						2				
Create Lobby Area							1							2				
Add Stadium Seating							1						2					
Exterior of Education Building	4												2					
Existing Breezeway	7																	
Create Glass / Windows Enclosur	<u> </u>	5																
Keep Open-Air		1																
Extend Canopy to Stairs		3																
Replace Awning / Canopy / Railin	1	5																
Wiggins House Entrance Remodel	1	3															5	
Add More Units																	2	
Parking Entry Welcome Area	1														4			
Create Covered Main Entrance	1										30				4			
Not an Option - Must Have											1							
Cosmetic Updates	_	-	5	-	_	15	2	8	40	31	-	3	7	14	24	10	10	
Cosmetic Updates Cosmetic Improvements	-	-	3	-	-	15		0	40	10	-	3	-		10		8	1
Flooring - Replace						12	2 -	8	32	6		3	5	7	10	3	2	1
Artwork - Update						12	- 2	0	32	2				/	10	3		
Furniture - Update							-		4	10				1	2	1		1
Remove Hallway Tile							1		7	10				1	1	1		1
Update Window Treatments							+			2					1			
Upgrade Classroom Counters / Sinks							1			<i>L</i>					1			
Reconfigure Choir Loft						1	1								1			
Floral Arrangements - Update						1	 			1								
Open Balcony with Smaller Seating						1	+			1								
Altar Area Refresh						1	+											
Improve Surface			5			1	+											
Updates			3				+		4					3				
	2	1		54		5	-	-	10	-			2	3	4	2		
Lighting Decembing Lighting Needs	_	ı	-	10	-	5	1	5	10	5	-	-	2	1	4	3	-	3
Lighting - Decorative Lighting Neede	iu I			10			-											
Lighting - Bell Tower Lighting				24			1											
Lighting - Safety / Security	2	1		19		5	1	5	10				2	1	1	2		2
Lighting - Update	Z	1		19)	I	3	10	3			Z	1	4	3		3

Saint Mark 2021 Survey / Q3-2022 Facility Master Plan Project List

Completed or In Process Projects
Captured in Q3-2022 Master Plan Project Inventory List, subject to revisions
Requires electrical / plumbing infrastructure investment to enable

Make Your Mark Day Projects
Continual improvements from operating funds or donor gifts, as available

Out Out	Ē				F			1		1	010						016		
Description		0.1			0.4		0.6	07. 4		0.0	Q10 -			012	014	015	Q16 -		010
Euroberging 19		•		· ·		055			00 117 1	ζ.		011 17	010					015	
Landscraping 19 4 9 22 -							-		`	•			`					`	l I
Landscoping		Exteriror	Breezeway	Playground	Lighting	Landscaping	Interior	Sanctuary	Hall	Interior	Room	Bridge	Restrooms	m	Bldgs	Bldg	Floor 1	Basement	Areas
Landscaping - Add Bright Freore for Hopolality 1	Landscaping	19	4	9	-	21	-	-	1	-	-	-	-	-	-	-	1	-	2
Landscaping - And Fruit Trees for Hospitality		12				1											1		1
Landscaping - Cardon Area	Landscaping - Add Bright Flowers in	3				6													
Landscaping - Intellal Sprintell System	Landscaping - Add Fruit Trees for Hos	spitality				1													
Landscaping - New Internace	Landscaping - Garden Area	1	1	8		3													
Landscaping - Trim / Remove Trees 3	Landscaping - Install Sprinkler System	1				2													
Add Larlywinth Create Outside Countyard (Frent) Create Outside County of Create Outsi	Landscaping - New Entrance					1													
Create Outside Courtyard	Landscaping - Trim / Remove Trees	3				4													
Decontive Fence or Wall	Add Labyrinth					3													
Install Planter Doves 2 1	Create Outside Courtyard								1										
Build Freed Courtyard (Front)	Decorative Fence or Wall		1																
Hespitality and Welcoming	Install Planter Boxes		2	1															
ADA Consideration S	Build Fenced Courtyard (Front)																		1
ADA Consideration S	Hospitality and Welcoming	1	10	21	-	-	15	2	9	-	3	5	-	1	6	4	4	2	1
Digital Bulletin Boards	ADA Consideration		5				1					4						1	
Rename Bridal Room to Gender Neutral	Add Coffee Station in Narthex Area						1												
Signage	Digital Bulletin Boards							1											
Signage	Rename Bridal Room to Gender Neutr	ral									2								
Security			5					1											
Have Bibles in Every Pew				1													1	1	1
Have Bibles in Every Pew	Sound, Technology, and AV System						11		7		1	1		1	6	4	2		
Have Bibles in Every Pew	Install Retractable Screens						1												
Playground	Have Bibles in Every Pew						1												
Playground - Replace Equipment	New Drinking Fountain								2										
Tables and Outdoor Seating	Playground																1		
General Maintenance	Playground - Replace Equipment			16															
Painting	Tables and Outdoor Seating	1		4															
Clean, Fressure Wash, & Paint 7	General Maintenance	8	21	7	-	4	8	3	5	5	3	-	-	8	1	1	3	2	-
Deep Clean Stained Glass Windows 1	Painting						9	5	12	4	4			3	8	9	5	5	1
Storage - Remove Unneeded Items 1	Clean, Pressure Wash, & Paint	7	21	7			2	1	1	2	1			2			2	2	
Replace Ceiling Tiles	Deep Clean Stained Glass Windows						1			1									
Repair / Touch up Pews and Woodwork	Storage - Remove Unneeded Items							1	4	2	2			6		1			
Repair Hymnal and Bible Holders	Replace Ceiling Tiles																1		
Refresh / Update / Maintain 1	Repair / Touch up Pews and Woodwor	rk					3												
Repair Lockers							1												
Other Recommendations 2 - 5 - - 4 2 2 - - 2 Add Refrigerator 1	Refresh / Update / Maintain	1				4	1	1											
Add Refrigerator 1 1 3 3 4 3 4 3 4 4 4 4 5 5 2 9 4 4 4 4 4 5 5 2 4 4 4 4 4 5 6 2 4 4 4 4 4 6 6 7 6 7 6 7 6 7	Repair Lockers														1				
Add Columbarium 2 Improve Drama Capabilities 3 2 8 2 2 Improve Drama Capabilities 4 4 5 5 2 3 2 3 2 3 2 3 2 3 3 3 3 4 3 3 4 3 3 4 3 3 4 3 3 4 3 3 4 3 3 4 3 3 4 3 3 4 3 3 4 3 3 4 3 3 4 3 3 4 3 3 4 3 3 4 3 3 4 3 3 4 3 3 4 3 3<	Other Recommendations	2	-	5	-	-	4	2	2	-	1	-	-	12	3	2	-	-	2
Create Multi-Function Space 5 2 8 2 Improve Drama Capabilities 4 9 Space Purpose / Room Assignments 2 2 Optimize Front Side Elevated Areas 1 9											1								
Improve Drama Capabilities 4 Space Purpose / Room Assignments 2 Optimize Front Side Elevated Areas 1		2																	
Space Purpose / Room Assignments Optimize Front Side Elevated Areas 1 2 2 2 Optimize Front Side Elevated Areas	Create Multi-Function Space			5				2						8		2			
Optimize Front Side Elevated Areas														4					
															2				2
Redo Stage Area							1												
	Redo Stage Area								2										
Youth Items - Pool table, Foosball, etc.).													1				
Seat Padding Added to Pews 3							3												
Stained Glass Window Display	Stained Glass Window Display															1			

Appendix A

Full Survey Results and Comments

					Su	rvev O1:	Overall ex	terior an	nearan	ce, buil	ding, aı	nd grou	nds.					
							or Capital Fund			,	ung, u	a grou	11451			Make Your Ma	rk Day Proje	ect(s)
	Major Upgrade					equires may	Improve	ing to Denve	-	Plumbing			Outdoor				ne Day 11 oje	et(s)
	& Renovation	Needs			Refresh	Add bright	Exterior of	Remove	Add	&		Front	Tables /	Replace	Columbariu	Clean, Pressure	Improve	Improve
Front locks good When anathropt construction complete	Needed	Maintenance	Fix Leaks	Parking	Landscaping	flowers	Educ Bldg	Trees	Garden	Electrical	Windows	Doors	Chairs	Railings	m	Wash, & Paint	Signage	Lighting
Front looks good. When apartment construction complete, screen the a/c equip																	,	
The overall exterior appearance is awesome.																		
Front of building good																		
Refresh exterior landscaping					1													.
Ok. Maybe add more bright flowers? Education building could use an exterior upgrade and						1	1											
painting							1										,	
Fit leaky roof, improve sound system																		
I'm satisfied with the classic look of Saint Mark.																		
Remove holly trees on 5th street and replace with a meditative garden								1	1								,	
over pretty good and inviting																		
New landscaping to update would be great					1													
We have a beautiful building!																		
We need a columbarium. I put together a brief proposal on															1		,	
this for Beth to share with trustees several years ago after my parents died. They put their ashes at Dunwoody UMC																	,	
in the columbarium and we wished we could do the same																	,	
at ST. Mark. The cost was about 10K for 100 spots and the																	,	
spots sell for 1000.00 each, so this would be a service to our members but also a capital fundraiser for the church.																	,	
Could go outside or could be in the changl along the back																		
pressure wash the building to removed the dirt and grime, fix the seals on all windows and doors																1	,	
Clear signage for parking (when available)																	1	
Always neat, clean and in good repair. Currently																		
appears very welcoming with attractive landscaping.																		
Overall looks pretty good																		
Fix the ever-present roof leak in the sanctuary on the 5th st																	,	
Update landscape and pain					1													
Looks attractive																		
Trim trees on 5th street and feature the windows. Better								1										
lighting of building and ground. Clean up anything that's getting shabby. Preserve the					1											1		
building.					1											1		
I'm in complete awe of the exterior beauty of St. Mark. It's a					1			1									,	
treasured piece of historical property and Atlanta. Howeve, when I look at our church I realize so much of its																		1
architectural grandeur is obscured by overgrown and																	,	
unsightly trees and aged shrubbery. For years I've felt the																	,	
holly trees that literally cover the 5th St. stained glass windows should be cut down. With these trees in place the																		ı
majority of the building's exterior beauty on that side is																		1
completely hidden. I also feel the majority of the 40-50 year																	,	
old shrubbery in the front of the church needs to be severely pruned or even replaced. I honestly believe the																		ı
original architects and the many skilled craftsmen who																	,	
contributed their talents to construct this masterpiece																		ı
would be saddened and hurt by its current appearance. It's my opinion that when people see this building they should																	,	
see only its architectural beauty and one-of-a-kind																	,	
craftsmanship. The majority of the trees and shrubbery on																		ı
the property are distracting. Months ago I Googled "magnificent historical cathedrals and churches" and it was																	,	
interesting how many pictures of such properties showed																	,	
buildings such as ours with minimal to NO tress or																		1
shrubbery close to the building. When people walk past our Paint project for the congregation or small group - paint																,		
doors, pressure wash, etc.																1	,	
New sod for the front lawn.																		
Educational Bldg Roof and Sanctuary Roof replacement,																		
along with sealing the granite to prevent leaks inside the All of the railings need to be replaced and steps														1				
refurbished with safety treads.														-				
Important that it's clean and well maintained with pressure																1		l
washing, painting and grout repairs as needed Complete overhaul of the landscaping. New exterior for the					1		1											
education building with updated windows																		
Lights, gardens, front steps that are easier to navigate (not just ramp availability).																		1
Need's to be upgraded front to back!	1																	
Decent, considering the age of the property, no major					İ													
changes needed Keep the traditional look of the building throughout.					 												go 9	
No opinion					 											Pa	ge 8	
F	l				1	L				L				1				

					Su	rvev O1	Overall ex	terior an	nearan	ce huil	ding a	nd grai	ınds					
							or Capital Fund			ice, buil	umg, a	iu grot	ilius.			Make Your Ma	rk Day Proje	ect(s)
	Major Upgrade						Improve	ling to Benit		Plumbing			Outdoor			Nunc Tour M	an Day 110j	(3)
	& Renovation Needed	Needs Maintenance	Fix Leaks	Parking	Refresh Landscaping	Add bright flowers	Exterior of Educ Bldg	Remove Trees	Add Garden	& Electrical	Windows	Front Doors	Tables / Chairs	Replace Railings	Columbariu m	Clean, Pressure Wash, & Paint	Improve Signage	Improve Lighting
Update the area new grass D	riccuca	Mannenance	1 IA Leuks	Turking	1	Howers	Luuc Blug	rices	Gurden	Electrical	W IIIdows	Doors	Chans	Runnigs	- III	wasii, ce raint	Biginge	Lighting
Look is old. Needs to be refreshed. Possibly a complete	1																	
redesign leaving stained glass windows. Maintain lawn and flower beds with attractive blooms and					1	1												-
greenery all year long. Paint red doors when needed.						•												
Keep it maintained, clean and beautiful																		
ok for the age, needs maintenance																		ļ
Looks good. I love the exterior in general																		
No opinion																		
The historic front of the building is an asset to																		1
Peachtree Street. However I think that the appearance of the church would be helped with an overall master																		
plan for landscaping, drainage, hardscape etc. The																		
landscaping on 5th street is dated and the hardscape is																		
in poor shape there as well. It would be more engaging for the community if there was some kind of entry from																		
the front of the church on Peachtree to make us look	1																	
like an active part of the community by reconfiguring																		
the Interactions Classroom to make an exterior entry.																		
The church looks empty and deserted during the week.																		
The need for burglar bars on the windows should be																		
reassessed and any not needed should be removed.																		
Repair the Roof																		
it looks good now																		
Repair/repaint red front doors												1				1		
fill window wells on chapel ramp, better looking											1							
covers for other window wells maintain the historical architecture																		
Fine.																		+
The one thing o would love to see is to have a															1			
memorial area where cremains could be placed the															-			
area next to the building in the back of the playground																		
fine as is																		
Excellent																		
Looks old and in need of maintenance, especially along 5th St.		1																
Good considering our current resources.																		ļ
keep traditional church look on outside, update							1			1								
education buildings, update plumbing and electrical the building looks great; more landscaping and					1													
planting outdoors would be nice (it is a little sparse); it					1													
looks really pretty when we have the Easter cross and it																		
would be a nice place to gather on Sunday mornings																		
Light on stained glass windows to show to outsiders																		1
Grass needs to be kept cut weekly Friday or Saturday					1											1		
so we shine on Sunday's. Pressure wash steps more				1														
often. Landscaper keeping up with the shrubbery and																		
flowers. We hold a very prominent prestigious address																		
and MIDTOWN and we need to shine from the outside Touch up painting																1		+
Strip and re paint front doors with new matching licks/					1							1				1		
hardware and decorative item on railing. Not pipes,					1							•						
Ideallin do new pavers / landscape Need																		
professional landscaping and service - not only look																		
better but sends the message we care about ourselves				1														
ang welcome others we want others to want to come				1														
in out doors to see more				ļ														
Church exterior is good. Landscape needs some care	ļ				1									ļ				ļ
Would love a little outdoor tables/chairs area	1			 									1	-				
Maintain the look	<u> </u>			 	1								-	1				<u> </u>
Exterior looks great Need more parking.	<u> </u>			1										-		-		
fix leaks, dramatically renovate education wing			1	1			1							 				+
including exterior			1				1											
-																		
Totals	2	1	1	1	12	2	4	3	1	1	1	2	1	1	2	7 Pa	ge 9 1	2

			Survey	Q2: Open	air bree	zewav h	etweer
		Rea		Capital Fundi			
	Major Upgrade	Replace	05	Create Glass /	Extend	1	Decorative
	& Renovation	Awning /	Make ADA	Windows	Canopy to	Keep	Fence or
	Needed	Canopy	Accessible	Enclosure	Stairs	Open-Air	Wall
eutify and paint							
eaning and a fresh coat of paint ear signage on how to enter the facility if the doors are							
lear signage on now to enter the facility if the doors are							
ould use some "cheering up"							
flore planter boxes to soften the breezeway.							
aint the iron, give a little facelift.							
Railing is rusted & should be replaced							
he breezeway could be cleaned more often as it tends to							
get used" by the local homeless population. sing concrete paint and filler to enhance entrance. Install							
planters with attractive plants							
mprove signage, Change canopy to clear plexiglass or		1					
similar to allow more light							
Covered path through a garden area.					1		
I think it could be freshened up a bit, but I've always thought we could make a really pretty glass enclosed				1			
Needs a cleanup and regular maintenance with pressure		1				1	
washing and paint or replacement of the awning between		•				1	
he buildings. It should remain open-air in my opinion.							
Acceptable, but probably needs to be upgraded as this is a major entry point to the building	1						
Completely redone. More accessible to handicap.	1		1				
rotection against eu d and rain.	•		·				
completely remove and replace. Add decorative fence or	1						1
vall that can secure entire area and prohibit homeless rom using as restroom.							
lemolish and redesign possibly with ramp. The ADA	1		1				
entrance at the back does not show respect to those with	-		-				
Enclose it (but install windows on either side). Replace the	1			1			
ulletin board with a digital sign. Enclose the breezeway.	1		1	1	1		}
Set rid of it. Replace or keep it open - it provides little	1	1		1			
rotection from rain	1	1					
Modernize the flooring, wall frescoes	1						
leeds to be upgraded and the canopy better designed to		1			1		
hield from rain. If we continue to have the stairs, consider							
overing them with the canopy. lot sure how to improve this. Can it be made			1				
nandicapped accessible?			1				
Perhaps an extension of the breezeway roof down the					1		
stairwell. Personally, I would like it to be closed off somehow to	1					1	
keep it cooler in the summer and warmer in the winter.	1						
Start over. That area is particularly ugly and will be more	1						
visable once people start parking in the future parking			ļ		ļ		
This could upgraded with a better-designed look and a handicap ramp.	1		1				
Jpdated awning		1	 		1	1	1
Jpgraded to provide a more tasteful entrance to the	1	1	 		1	1	1
Vould be good to enclose this with one entrance and	1						
nake the playground an enclosed multipupose atrium as	1						
roposed in master plan in the nineties. his area needs to be made ADA compliant. There needs			ļ				
be a way to access the office area/Wade Hall from the			1				
ducation building and vice versa. Not having ADA							
ccess limits how we can use this area for ministry and							
nconveniences those differently-abled. The fire escape							
from the second floor needs updating - it is rusted out in							
some places and is unsightly.				l .	I	<u> </u>	1

	Survey Q2: Open air breezeway between the offices and the education building.												
		Req	uires Major	Capital Fundin	g to Deliver				Mak	e Your Mark	Day Project	:(s)	
	Major Upgrade & Renovation Needed	Replace	Make ADA Accessible	Create Glass /	Extend Canopy to	Keep Open-Air	Decorative Fence or Wall	Clean, Pressure Wash, & Paint	Improve Signage	Improve Lighting	Install Planter Boxes	Address Rust Issues	Garden Area Created with Covered Path
It seems to me that this is not a very warm and welcoming entrance. Could there be some way to make the post and breezway less industrial, and more like the rest of the building. Maybe cap the poles in stone pillars? Strip the old paint off and repaint. Repair the bulletin board or enclose a screen with announcements	1							1	1				
new bulletin board framing, repaint all metalwork repaint the railings, fencing and roof								1	1				
Needs paint and refreshment. Secure access to the back steps/landing? All iron work needs repainted.								1				1	
Needs total replacement; unsightly.	1												
keep but update It's not visually attractive; it looks dated so a refresh here would be good.	1												
Upgrade, change out rusty metal	1											1	
Painted and update bulletin board.								1	1				
Improve lighting to elevator area										1			
Needs complete re-do - prime rust and paint dark at a minimum	1							1				1	
Functional so not high priority													
Would be nice if it were enclosed as an all weather space				1									
Enclosed to improve movement between buildings. Totals	19	5	5	1 5	3	1	1	16	5	1	2	5	1

Survey Q3: The Courtyard (Playground)

		Requires I	Major Capi	tal Funding	to Deliver		Make Y		k Day Pro	ject(s)
		Major		Create	Add Tables	Improve		Clean,		
	Replace	Upgrade &		Multi-	and	Privacy for	Garden	Pressure	Address	Install
	Playground	Renovation	Improve	Function	Outdoor	Security of	Area /	Wash, &	Rust	Planter
	Equipment	Needed	Surface	Space	Seating	Children	Landscape	Paint	Issues	Boxes
Refresh				-				1		
Landscaping and improved			1				1			
Iron railings and bars need touching								1	1	
Could we add a small urban garden							1			
space? If not here, somewhere?										
Update playground equipment; paint	1						1	1	1	1
and add greenery										
Addition of a picnic area for the					1		1			
staff. Evaluation of the uses of the										
area with considerations for a										
Not sure of the bark/rubber in that			1				1			
area, but probably needs more.										
Maybe a garden area between play										
set and the back door of the cafeteria										
I don't know how much this space is								1		
utilized. If we have children that use										
it and enjoy it REGULARLY then it										
should be maintained.										
Move playground equipment to		1								
North side of building, lower grade										
to Wade Hall level, and make this										
the main entrance to Wade Hall.										
Update equipment to allow multi	1			1						
useperhaps playground equipment										
that can be moved to allow use of										
the courtyard as a multi-function										
outdoor event space										
It would be nice to have the fence a						1				
little more private for the safety of										
the children.										
New playground equipment.	1									
Install new swings, possible maze	1									
the kids to play in										
See 2 a multiputpose enclosed		1		1						
atrium as proposed in ninties										
masterplan										Page

Survey Q3: The Courtyard (Playground) **Requires Major Capital Funding to Deliver** Make Your Mark Day Project(s) Major Add Tables Clean, Create Improve Upgrade & Replace Privacy for Pressure Multiand Garden Address Install Playground Renovation **Improve** Outdoor Security of Area / Wash, & **Function** Rust Planter Equipment Needed Surface Space Seating Children Landscape Paint Boxes Issues worn out Cover a portion of it and update the 1 play equipment. We desperately need a small area for outdoor seating (picnic table, bench, etc.) for adults. Needs new equipment, flooring. 1 Consider for it to enclose at multiple floors, including sanctuary so it is Needs to be updated if it's used regularly. If not, consider updating to a patio so it can be used as an outdoor meeting space similar to the Havwood patio. If the courtyard is going to continue 1 to be the playground, the equipment and toys need to be updated. Playground needs an update. Ideally 1 we would have playspace for the littler children and a separate outdoor space for the older children. There should be some elements that are inclusive for all needs. I think it should be relocated on the 1 other side Update the area 1 Ugly!! Playground equipment needs to be replaced. Replace "grass" or take out and paint 1 concrete. Replace playgroung equipment IF the area is ever would like to see it updated and 1 opened up It could use some better equipment 1

for the kids to play on.

				Survey Q3:	The Courty	ard (Playgro	ound)			
		Requires	Major Capi t	tal Funding	to Deliver		Make Y	our Marl	x Day Pro	iect(s)
		Major		Create	Add Tables	Improve		Clean,	<u>.</u> /	
	Replace	Upgrade &		Multi-	and	Privacy for	Garden	Pressure	Address	Install
	Playground	Renovation	Improve	Function	Outdoor	Security of	Area /	Wash, &	Rust	Planter
	Equipment	Needed	Surface	Space	Seating	Children	Landscape	Paint	Issues	Boxes
This area is in need of a complete	1	1		•			Î			
overhaul. It is not a safe place for										
children to play and run around with										
the window wells into Wade Hall.										
The playground equipment is dated										
and needs to be replaced.										
could be updated if we plan to		1								
pursue families with young children										
New flooring and new play ground			1							
equipment										
commercial swing set with proper	1				1		1			
mulch, picnic table										
This is a part of the church that	1	1								
could use a serious face-lift. If we										
want to be around for another 100										
years, Saint Mark needs to invest in										
the appearance and quality of areas										
for the children and youth! The										
playground should be completely										
overhauled and updated so children										
and young families feel prioritized										
Put a memorial garden in th back							1			
next to the building for cremains										
needs something		1								
Average		1								
All the playground equip. needs	1				1					
replaced. Add an adult picnic table										
be added?										
Necessary? Could be repurposed for									_	
better use, I'd imagine.										
keep but update		1								
The playground should be updated		1								
Updated		1								
Check any safety hazards										

				Survey Q3:	The Courty	ard (Playgro	ound)			
		Requires 1	Major Capi	tal Funding	to Deliver		Make Y	our Marl	k Day Pro	ject(s)
		Major		Create	Add Tables	Improve		Clean,		
	Replace	Upgrade &		Multi-	and	Privacy for	Garden	Pressure	Address	Install
	Playground	Renovation	Improve	Function	Outdoor	Security of	Area /	Wash, &	Rust	Planter
	Equipment	Needed	Surface	Space	Seating	Children	Landscape	Paint	Issues	Boxes
Would love to relocate - repurpose		1		1						
this area to be used for social a DJ										
programs functions. Ideally lover the										
grade - open off of wade hall and										
education										
Needs to be more Inviting for		1								
Third. The playground is important	1	1								
to attracting families with young										
children. The equipment needs to be										
Make something more useful to all -				1						
such as a BBQ area.										
How often is it used?										
Continue to maintain equipment and		_	_				1	1		_
ground covering										
Total	16	20	5	5	4	1	8	5	2	1

Survey Q4: Exterior Lighting

			Security Lie	ghting Focus	, 8	
	Motion	C-f-t/	Security Lig	gitting Focus	Decorative	
		Safety /				
	Sensing	Security	Add More	Bell Tower	Lighting	LED
	Flood Lights	Lighting	Lighting	Lighting	Needed	Lighting
At a minimum, highlight the bell tower. Compete lighting			1	1		
of Peachtree façade would be great.						
Need better lighting on the stairs leading from Fifth Street			1			
of the Entrance of the sanctuary						
Increase for security and to highlight the main bldg. at		1	1			
Could add more motion sensing floods in rear parking lot(if still there?).	1					
Dramatic decorative lighting, plus good security lighting.		1			1	
Change all to LED and add more		_	1			1
Adequate safety lighting		1				-
More lights might increase safety. I love how the building		1				
is lit and visible from Peachtree, and am thinking of more		1				
lights on the other parts of the building						
Upgrade and use more motion sensors	1					
Improve so that new circular drive and all entances are	1	1				
well lit at night without being too bright. Motion activated		1				
lights in less active exterior spaces such as south side of						
ed bldg. Parking deck should be very well lit and I think						
that should involve a light color coating (dirt resistant,						
siliconized) on interior concrete and surfaces. Bright is						
also more welcoming						
Need more for after dark events		1	1			
Add more			1			
Lighting has improved over the years. Motion sensitive	1					
lighting would be a nice addition.	1					
Around front, feature architecture. For security reasons,		1	1		1	
address the south side.						
To enhance the look of the building. Perhaps inside lights					1	
shining on the stained glass windows at night so they will						
show up from the street.						
Evaluated to best display the church after the tower		1	1			
behind is constructed to see what lighting needs to be						
added to avoid any dark spots on the property.						4
Yes better lighting to flood the church's exterior.		1	1			1
Brighter - maybe LED flood lighting		1	ļ			1
Important to use latest cost efficient bulbs for street		1				1
presence at night and as a vandalism deterrent.						
Lighting the exterior of the building would be amazing.					1	
Could we update and add lighting in the sanctuary that						
would illuminate the stained glass at night?	<u> </u>		<u> </u>			

Survey Q4: Exterior Lighting

			Security Lie	ghting Focus	, 8	
	Motion	Safety /	Security En	Julia de la sectiona della sectiona della sectiona della sectiona de la sectiona della sectiona	Decorative	
	Sensing	Security	Add More	Bell Tower	Lighting	LED
	Flood Lights	Lighting	Lighting	Lighting	Needed	Lighting
Bright at night, warm and welcoming in the day. Light all	8	1	1	8 8		8 8
areas that look and/or feel like hiding spaces. Utilize the						
lighting to work with green space/gardens and at the						
same time provide security protection		-				
Complete security lights fir safety		1				
This could be brightened up/ added to for better security.		1				
For security- the more the better!		1	1			
We need SignifyHealth exterior lighting that will showcase the exterior beauty of this structure at night!!!					1	
What I think is most important for exterior lighting is		1				
for security.						
looks fine. could be more dramatic. Interior lights					1	
shining through stained glass into the world outside						
Good						
Could use more so the church is better-lit at night for		1				
safety purposes.						
Lighting so that the windows could be lighted at					1	
night services						
fine as is						
Good						
Enhance lighting of the building			1			
Insufficient given our location and security concerns.		1	1			
update for security and efficiency		1				
Adding more uplights outdoors would be good.					1	
Show off our building					1	
LED as needed						1
Have consistent, matching warm / welcoming color					1	
temperature lighting						
Needs major upgrades. Which may also help with		1	1			
ongoing security issues						
Fourth. Exterior lighting is important for security. I		1				
haven't been by the church at night in a while so I						
don't know if the lighting is good or bad. But I						
assume it could be improved being on this list.						
Seems ok						
Totals	3	21	14	1	10	5

Survey Q5: Exterior Landscaping

			Requires	Major Capit	al Funding t	o Deliver				· Mark Day ect(s)
	Need Design					New				Add Bright
	Plan for				Install	Entrance	Add Fruit		Refresh /	Flowers in
	Complete		Gardens	Add	Sprinkler	Landscaping	Trees for	Larger	Update /	Bushes /
	Overhaul	Trim Trees	Needed	Labyrinth	System	Needed		Plant Beds	Maintain	Signage
Refresh				,	,				1	9
Maybe add more bright flowers n										1
bushes.										
Updating and maintenance									1	
Add more color (spring flower beds,										1
etc.). Add short fencing around the										
tree near the 5th Street door and										
plant some shrubs or flowers.										
Just keep it neat and trimmed.									1	
bulbs, flowers in the front flower										1
beds on P'tree, playground needs										
some attention maybe cutting back										
some bushes and/or limbs										
Seasonal flowers around street										1
marquis and regular maintenance of										
shrubbery and other perennials.										
Nothing need to be over the top with										
landscaping.										
Green space! Gardens, flowers,			1	1						1
labyrinth path										
More colors in and around the										1
church. Make it's appearance one										
that people want to come in and see										
what is happening.										
When apartment construction						1				
complete, landscape at the building										
entrance.										
The front looks good, can't										
remember the sides										

Survey Q5: Exterior Landscaping Make Your Mark Day Requires Major Capital Funding to Deliver Project(s) Need Design Add Bright New Plan for Add Fruit Refresh / Flowers in Install Entrance Add Bushes / Complete Sprinkler Landscaping Trees for Larger Update / Gardens Overhaul Trim Trees Needed Hospitality Plant Beds Labyrinth System Needed Maintain Signage 1 adding small fruit trees so that we 1 1 having a place people passing could write their prayer requests for us? 1 Hollies on 5th street have grown too smallrr scale planting coordinated Have a design and plan to beautify 1 Trim 5th street trees. selective trim 1 1 1 1 begun, but increase the front bed to the side of 5th street. And cut down the large holly bushes also on the 5th street side. And install an irrigation Complete overhaul of landscaping

Update where practical. Perhaps

can extend hospitality to those passing by when fruit is in season Could we add a labyrinth? Or a

prayer garden with a feature of

Similar to current front of church.

big and should be replaced with

of front to see more of building. Continue the landscaping work

Need's to be addressed

Landscaping should be on a much

small scale. The landscaping should complement the structure, but take

Update

away from it.

1

1 1

1

with front.

				Maka Vau	Mork Day					
			Requires	<mark>Major Capit</mark>	al Funding t	o Deliver				Mark Day
	Need Design					New			Proje	Add Bright
	Plan for				Install		۸ مأمأ ⊏سنئه		Defreeb /	_
					Install	Entrance	Add Fruit		Refresh /	Flowers in
	Complete		Gardens	Add	Sprinkler	Landscaping	Trees for	Larger	Update /	Bushes /
	Overhaul	Trim Trees	Needed	Labyrinth	System	Needed	Hospitality	Plant Beds	Maintain	Signage
I think that the appearance of the church	1									
would be helped with an overall master plan										
for landscaping, drainage, hardscape etc.										
The landscaping on 5th street is dated and										
the hardscape is in poor shape there as well.										
what we have is fine. we have a very										
minimal outside area anyway										
Great. Could we add a prayer garden in front			1							
of the Ed building and behind the chapel.										
This could be fenced in with benches and										
perhaps the back of the chapel used as a										
columbarium area.										
cut down 5 Foster holly trees on 5th St,		1								
prune other hedges down so homeless cannot										
poop/pee behind them										
Beautiful. More flowers are always a plus!										
very nice as is , please don't chop down any										
trees!!!										
Good										
Add water irrigation system. Could water					1					
from hvac condensation lines be utilized?										
Needs a refresh	1									
Good, considering our resources.										
add more flowers grass								1		
More plantings out front would be nice								1		
Is there room to do a labyrinth, even a small				1						
one										
Read question ones answers										
Continue good work									1	
See #1										
Upgrades to keep dog walkers off the grass	1		_		_			_		
Flowers								1		
Total	8	4	3	3	2	1	1	4	4	6

Survey Q5: Exterior Landscaping

	Survey Q6 Sanctuary interior, including vestibule, balcony																										
										Requi	res Major	Capital Fu	nding to I	Deliver	_									Make You	ır Mark D	ay Project((s)
								Sa	anctuary										Narthe	x / Vestibule		Bal	cony				
	Plaster Repair	Fix Window Leaks	Improve Sound System / Technolog	Carpet Replacem	Repaint Same/Sim ilar Colors	Repaint New Colors	Repair / Touch up Pews and Woodwork	Seat Padding Added to Pews	Update Lighting (Possibly LED)	Refinish Floors	Deep Clean Stained Glass Windows	Optimize Front Side Elevated Areas	Altar Area Refresh	Repair Hymnal and Bible Holders		Reconfig ure Choir Loft	ADA Considera tions	Replace or Remove Carpet	Update Light Fixtures	Narthex Renovation / Expansion	Restore Doors	Remodel /	Open Balcony with Smaller Seating	Add Coffee Station in Narthex Area	Have Bibles in Every Pew	Clean	Stop Taping Items to Walls
Plaster repair. Repaint same	1		,		1				,													18					
or similar colors. Sound system in bad need			1																								
of upgrade. Certain areas of			1																							,	
the sanctuary it is very hard																										, '	
to hear the speaker																										<u> </u>	
Repair leaks on walls.	1	1																								,	
Particularly the North Wall Repair n paint to sanctuary	1	1																									
arch plaster(likely already on	1	1																		1						1	
the list), and fix roof/gutter																				1						1	
leak causing it. Really like all																										1	
else, beautiful.				ļ	1	-														 		-	—	-			
Water damaged plaster should be repaired.	1																									1	
Paint interior and repair	1	1	1	1				1																			
plaster around windows, new	1	•	1					1																		,	
carpet ,seat padding for all																										, '	
pews, new sound system																										'	
Get rid of carpet in vestibule, change all lights to LED, add																		I	1					I		,	
a coffee/tea station to the																										,	
room off the																										<u>. </u>	
The sanctuary could use							1																			,	
touching up a bit. woodwork,																										, '	
some of the pews. Window leaks fixed, plaster	1	1		1		1																					
fixed and a new updated	1	1		1		1																				,	
color palette for new carpet																										, '	
and paint																										<u>'</u>	
Maintenance on the plaster	1																									,	
redo all the plaster. Fix the	1	1		1																							
leak that causes the plastert																										, '	
to fall. new carpet Fix the plaster spots that	1																										
have been there for years.	1																			1						1	
Fix the water problem	1	1					1							1											1		
causing the problem around																				1						1	
the stain glass windows;																										,	
Repair or replace pews - the																				1						1	
need to be anchored to the floor, fix hymnal and Bible																				1						1	
holders; Bibles need to be in																										1	
every new several are																				ļ						ļ'	
Repair leaks, replaster and	1	1			1																					1	
repaint. Otherwise I like it. It seems ok - the windows					1								1	-				1		1	1		\vdash			$\overline{}$	
are majestic and I love the													1							1						1	
pews. The altar area seems																										1	
a little plain.				ļ																ļ						ļ	
Repair the wall and ceiling	1	1																		1						1	
over and around stain glass windows on 5th street side																										1	
and ceiling over choir loft																				1						1	
fix leaks, paint, refinish floors		1			1					1																	
	l	•	l	l		I	l	<u> </u>				l					1		1	<u> </u>	<u> </u>	1					

	Survey Q6 Sanctuary interior, including vestibule, balcony																										
										Requi	res Major (Capital Fu	nding to I	Peliver										Make You	r Mark D	ay Project((s)
								Sa	anctuary										Narthex	/ Vestibule		Balo	cony				
	Plaster Repair	Fix Window Leaks	Improve Sound System / Technolog y	Carpet Replacem ent	Repaint Same/Sim ilar Colors	Repaint New Colors	Repair / Touch up Pews and Woodwork	Seat Padding Added to Pews	Update Lighting (Possibly LED)	Refinish Floors	Deep Clean Stained Glass Windows	Optimize Front Side Elevated Areas	Altar Area Refresh	Repair Hymnal and Bible Holders	Install Retractabl e Screens	Reconfig ure Choir Loft	ADA Considera tions	Replace or Remove Carpet	Update Light Fixtures	Narthex Renovation / Expansion	Restore Doors	Remodel / Upgrade	Open Balcony with Smaller Seating	Add Coffee Station in Narthex Area	Have Bibles in Every Pew	Clean	Stop Taping Items to Walls
Improve/update/repair sanctuary sound system. Utilize shorter pews in the balcony to open the space; figure out a way to enlarge the vestibule (narthex). Remove the wall between the narthex and the old brides room to open up the space. Repaint and update the narthex light fixtures (the current color and carpeting looks dated). The sanctuary is beautiful as is. Determine a more effective way to use the 2 elevated areas on either side of the front (where the Chrismon tree is placed on the left and the piano is located on the right). Figure out a way to install inconspicuous			1									1			1			1	1	1			1				
Wish we can expand the narrhex to the front but historic nature may not allow for it. One option for sizable gatherings space is off corridor between sanctuary and chapel, expand into courtyard (fire stair area). Or continue down that corridor and open up brides' room																				1							
Clean up the shabby. Well maintained original is good.																										1	
Repairs to the structure to prevent the water incursions that continue to damage the interior walls of the	1	1																									
once leaks have been resolved, replaster and paint areas around windows in Sanctuary	1	1																									
Replaster the entire interior, deep clean stained glass windows, replace flooring & add cushions to pews	1			1				1			1																
Painting repairs as needed. Please stop taping items to the walls. Plaster repairs and continuing leaks need to be addressed as these are most likely causing future archlems which aren't visible.	1	1			1																						1

										Sui	rvey Q6	Sanctu	ary int	erior, in	cluding	yestibu	ıle, bald	cony									
											res Major (-						Make You	r Mark D	ay Project((s)
								Sa	ınctuary										Narthe	/ Vestibule		Balo	cony				
	Plaster Repair	Fix Window Leaks	Improve Sound System / Technolog	Carpet Replacem	Repaint Same/Sim ilar Colors	Repaint New Colors	Repair / Touch up Pews and Woodwork	Seat Padding Added to Pews	Update Lighting (Possibly LED)	Refinish Floors	Deep Clean Stained Glass Windows	Optimize Front Side Elevated Areas	Altar Area Refresh	Repair Hymnal and Bible Holders		Reconfig ure Choir Loft	ADA Considera tions	Replace or Remove Carpet	Update Light Fixtures	Narthex Renovation / Expansion	Restore Doors	Remodel / Upgrade	Open Balcony with Smaller Seating	Add Coffee Station in Narthex Area	Have Bibles in Every Pew	Clean	Stop Taping Items to Walls
leaks in the roof/ walls need to be fixed The sanctuary needs to be updated. New carpet and paint (new color). The choir loft is awkward and needs to be reconfigured to seat the choir. Updated lighting and sound system. Is the rail in the balcony to code? New carpet and paint in the vestibule.		1	1	1		1		76.15	1							1		1		2.74	1	o _{pg} , and		71100	1011		
The balcony need's to be																						1					
remodel- Upgrade Aesthetically attractive and appropriate for its use, no changes or upgrades needed other than fixing and repainting the chronically leaking cellings	1	1																									
Improved auditory system			1																								
within the sanctuary. Elevators, handicap access,																	1										
eliminate stairs, No. #1 priority should be to repair leak and repair plaster	1	1																									
walls and paint The interior ceilings, walls need repair, better sound system	1	1	1																								
Repair water damage on	1	1																									
sanctuary walls. fix water spots	1	1																									
A "final" fix for the pointing and plaster and repainting.	1	1																									
Areas need repair (water damage) around the stained windows	1	1																									
Needs plaster work, paint(last paint was uninspiring and plain).	1	1		1		1			_			-													•		
The vestibule/ narthex could use some more lighting. It is dark and dreary looking when people enter, especially at night. Of course, as we all know, the deteriorating windows. The hallway to the chapel and the main hallway to the		1																	1								
I wish we could fix the mystery leak and paint the patches thats bothered me for years well I guess its still there last time I was actually in the church was	1	1																									

Survey Q6 Sanctuary interior, including vestibule, balcony Requires Major Capital Funding to Deliver Make Your Mark Day Project(s) Narthex / Vestibule Balcony Sanctuary Improve Optimize Add Deep Open Sound Repaint Repair / Seat Update Clean Front Repair Replace Balcony Coffee Have Stop Same/Sim Padding Lighting Install Update Bibles in Fix Touch up Side Reconfig ADA Narthex with Station in Taping System / Carpet Repaint Stained Altar Hymnal or Plaster Window Technolog Pews and Added to (Possibly Refinish Glass Elevated and Bible Retractabl ure Choir Considera Light Renovation Narthex Every Replacem ilar New Area Remove Restore Remodel Smaller Items to Woodwork Pews LED) Floors Refresh Holders Loft Clean Walls Repair Leaks Colors Colors Windows Areas Screens tions Carpet Fixtures Expansion Doors Upgrade Seating Area Pew While the traditional appearance of the sanctuary needs to be respected, I would like to see an upgrade to the technology in the Sanctuary. The sound system needs to be upgraded and we need to have integrated video capability that can be It would be very nice if we could be able to repair the water damage near the windows. it's good, but we need to stop the water coming in through the middle Refinish all wood work and new paint after water problems and plaster are fixed. New carpet in the sanctuary and balcony to match the vestibule. Brighter lighting. Technology friendly repair plaster, repaint (same or similar colors, I The walls and the plaster need fixing. I believe that also requires fixing the issues with leaks. fix the water damage & stain. maintain the The leak in the sanctuary roof must be addressed so the plaster bubbling can be addressed as well to preserve our beautiful sanctuary. Repair the falling plaster the Sanctuary IS Saint Mark . Don't change Good Repair wall damage from water leaks. Improve Looks good although there are leak issues Much deferred maintenance needed, but on the whole, serviceable new red carpet and fixtures, repair and repaint

Survey Q6 Sanctuary interior, including vestibule, balcony Requires Major Capital Funding to Deliver Make Your Mark Day Project(s) Narthex / Vestibule Balcony Sanctuary Improve Optimize Add Deep Open Sound Repaint Repair / Seat Update Clean Front Repair Replace Balcony Coffee Have Stop Same/Sim Touch up Padding Lighting Update Bibles in Side Install Reconfig ADA Narthex with Station in Taping Fix System / Carpet Repaint Stained Altar Hymnal or Plaster Window Technolog Pews and Added to (Possibly Refinish Glass Elevated and Bible Retractabl ure Choir Considera Light Renovation Narthex Every Replacem ilar New Area Remove Restore Remodel Smaller Items to Woodwork Pews LED) Floors Refresh Holders Loft Clean Walls Repair Leaks Colors Colors Windows Areas Screens tions Carpet Fixtures Expansion Doors Upgrade Seating Area Pew repair of the north wall; maintain regular maintenance schedule to prevent future water incursion The downstairs of the sanctuary is nice; the balcony is a little utilitarian and I recall had a lot of cords and things on the ground up there which should be cleaned up; the carpet in the sanctuary should be updated; the plaster has water damage that is visible. Stop the leaks Fix the water leak that's causing the plaster to fall off on the fifth Street side of the sanctuary. Cleaning per COVID protocol Repairs needed, permanently fix water issues. When funds allow get new carpet, new organ screen drapes (ours dates 70's look), Possible taster full screens - could be large on on nice black iron mobile posts. Looks fine except for water damage areas First I would say are the sanctuary walls where there is some water damage. Mostly to make sure there is not more Just update, but keep the look and feel. I know we have spent a fortune trying to solve water damage on north wall and above choir but still is an issue. Maybe we strip the plaster off, expose the granite and just secure the windows. New Pews that dont crack and squeeze and padded. repair damage around

windows

										Su	rvey Q6	Sanctu	ary int	erior, ir	cluding	vestibu	ıle, balc	cony									
										Requi	res Major	Capital Fu	nding to I	Deliver										Make You	r Mark Da	y Project((s)
								Sa	anctuary										Narthex	/ Vestibule		Bal	cony				
			Improve								Deep	Optimize											Open	Add			
			Sound		Repaint		Repair /	Seat	Update		Clean	Front		Repair				Replace					Balcony	Coffee	Have		Stop
		Fix	System /	Carpet	Same/Sim	Repaint	Touch up	Padding	Lighting		Stained	Side	Altar	Hymnal	Install	Reconfig	ADA	or	Update	Narthex			with	Station in	Bibles in		Taping
	Plaster	Window	Technolog	Replacem	ilar	New	Pews and	Added to	(Possibly	Refinish	Glass	Elevated	Area	and Bible	Retractabl	ure Choir	Considera	Remove	Light	Renovation /	Restore	Remodel /	Smaller	Narthex	Every		Items to
	Repair	Leaks	у	ent	Colors	Colors	Woodwork	Pews	LED)	Floors	Windows	Areas	Refresh	Holders	e Screens	Loft	tions	Carpet	Fixtures	Expansion	Doors	Upgrade	Seating	Area	Pew	Clean	Walls
Fix damaged plaster once	1		1																								
leaks are fixed; consider																											
addition of technology to																											
allow for diverse use of the																											
space/worship experiences																											
Totals	42	30	11	0	6	3	3	3	2	1	1	1	1	1	1	1	1	3	3	2	1	1	1	1	1	1	1

		Survey Q7 below sanctuary interior Requires Major Capital Funding to Deliver Make Your Mark Day Project													
				Re	quires Ma	jor Capital	Funding	to Deliver					Make Y	our Mark l	Oay Project(s
	Update Restrooms / Plumbing		Repair Damaged Areas	Create updated Conference Room / Classroom (could rent)	New Carpet	Signage	Update Lighting	Improve Water Dispenser s	Elevator from Sanctuary to Lower Levels	Digital Bulletin Boards	Remodel Work Room	Create Lobby Area	Repai		Address Storage Overflow
Replace all restrooms with single stall gender neutral restrooms.	1														
The restrooms need to be updated, lighting improved in hallway from sanctuary to Wade Hall Bathrooms could use updating with no water urinals and toilets with dual flush and turn on hot water	1														
Desperate need for updated restrooms	1														
Update lighting restrooms need upgrading. maybe install electric hand dryers. conference room needs touching up	1						I								
New carpet and paint					1								1		
Love the all gender restrooms. Can we create a family restroom with changing table if we don't have one or two? Are we able to create conference room type spaces that the community can reserve? I did that at Mt Vernon UMC in Washington DC for a national conference and it was great!	1			1											
Replace old urinals n toilets w low use units, saves a ton in water bills and good for environment. Run new cold CPVC or PEX lines to new drinking fountains and stop using bottled water(waste of money n time).	1							1							
Upgrade plumbing and fixtures	1														
Keep paint fresh particularly in halls. This will require establishing a regular schedule of repainting. Pay particular attn to areas such as corners that wesr quickly. Historic 5th st doors have rot at the bottom that needs immediate attention.			1										1		
Lots of ideas here! Elevator access from the sanctuary; determine better use of the space where the unused bulletin boards are located on either side of the entrance to Wade Hall (replace with digital bulletin boards). Remodel the work room (currently it's used more for storage for rarely used items than anything else. If items were relocated, the equipment used more regularly (copiers, paper folder, etc.) would not require as much space. Replace the shelving over the long counter with enclosed cabinets. if the church office space was reconfigured, we would probably have room for a small 'lobby' / welcome area in place of Jim or Christia's office. Relocate the items in the Outreach room; return it to office space (at one point it was Kimberly Broerman's office); Make the 5th Street door accessible from outside the church. Update the area inside the main office entrance (near Christia and Jim's office) so that it is more attractive and welcoming. renovate heads record and inserted the instance to the second of	1				1				1	1	1	1			
reception area IF this remains our main entrance.	1		1										1		
Make them clean and neat. Fresh paint. Repair damaged areas. A complete redo, possibly moving the offices to the educational building and bringing them into the 2020's. Update Restrooms throughout the Bldg.	1	1	1										1	1	
Bathrooms need to be renovated	1												-	_	+
Maintain and update as needed for cleanliness without losing the historical character of the spaces	1														
Gut it and start over to modernize and bring to code. Create a more welcoming entry at offices.		1													
Stop using spaces as overflow storage - find or build appropriate storage and allow rooms to be welcoming for intended usages Upgrade		1													1
Update areas		1												Page 27	

	Survey Q7 below sanctuary interior Requires Major Capital Funding to Deliver Make Your Mark Day Proj														
				Re	<mark>auires Ma</mark>				cuu j				Make Yo	ır Mark Da	v Project(s
				Create updated	1	,			Elevator						
	Update Restrooms	Complete Remodel	Repair Damaged	Conference Room / Classroom	New		Update	Improve Water Dispenser	from Sanctuary to Lower	Digital Bulletin	Remodel Work	Create Lobby			Address Storage
	/ Plumbing			(could rent)	Carpet	Signage	-	_	Levels	Boards	Room	Area	Repaint	Clean	Overflow
Restrooms very small and hard to find.	1	10			•	1							•		
Rennovate the Bathrooms off Wade Hall	1														
Go back to mens and ladies bathroom not unisex	1														
Restrooms, conference rooms all need updating desperately	1			1											
The end with the offices is ok, but the other end of this floor just feels kind of dated and stuffy.		1													
The offices should be relocated to either close to a Peachtree		1			1										
Street entrance or to the main entrance near where the new															
parking deck will connect. It is time for an overhaul of what is															
currently used as office space. The walls need to be repaired															
(especially exterior walls damaged by water) and repainted.															
The carpet in the offices needs to be assessed for replacement.															
The bathroom facilities also need to be renovated and															
modernized. The windows need to be examined for															
replacement (some only have plexiglass in the panes instead of															
plain glass or double paned glass) These spaces actually could															
be repurposed to expand the bathrooms or be used as	1														
restrooms are always a issue. could definitely be updated Repainting all over, modernize the restrooms and strong	1												1		
technology for offices	1												1		
gut & replace restrooms, get air vents in conference room,	1												1		
repaint															
Restrooms could us a major overhaul. More gender neutral	1														
bathrooms would be in keeping with our "all are welcome"															
theology.									1						
It would more welcoming for us to have elevator access from	1	1		1					1						
the Sanctuary directly to Wade Hall. No one should have to walk outside in the rain, cold, or heat to get to activities in															
Wade Hall. Restrooms could use an overhaul with stalls that															
actually LOCK. Offices should be moved to the second floor															
of the education building once breezeway is made connecting															
the parking deck and offices should be re-purposed for														1	
conference rooms or storage for A/V or other misc. needs.															1
okay as is.															
Average															
Update all bathrooms with new fixtures & low flow toilets	1														
Restrooms need major overhaul / replacement (esp.	1	1													
considering ADA requirements). Offices are cramped and															
insufficient from my perspective for our hard-working staff.															
renovate		1												1	igsquare
The restrooms need to be updated	1													ļ	
Pastor's study. He deserves something nice and roomy		1							-					+	
Update and bring a bit more modern.		1							-				-	1	\vdash
Cleaning per COVID protocol Pain all white walls with warmgrey doors/ trim to look clean,	1							-					1	1	\vdash
elegant (no yellow) red owl al EDU building - stat with main	1												1		
level - new commercial restrooms. Too much to write here															
All restrooms need to be upgraded	1													2000	
Conference room	1			1										Page 28	
<u> </u>				-		·		1							

								ow sanc	tuary in	terior		
				Re	quires Ma	jor Capital	Funding 1	to Deliver				
	Update Restrooms / Plumbing		Damaged	Create updated Conference Room / Classroom (could rent)	New Carpet	Signage	Update Lighting	Dispenser	Elevator from Sanctuary to Lower Levels	_	Remodel Work Room	Create Lobby Area
Update.	, I tullioning	1	111000	(Coura rent)	carper	Signage	Lighting	J	Develo	Douras	rtoom	- 11100
Seem functional												
Update restrooms	1											
Modern restrooms; upgraded kitchen to reflect current needs (assuming it doesn't currently		1										
Totals	28	12	3	4	3	1	1	1	2	1	1	1

Make Your	· Mark Da	y Project(
Repaint	Clean	Address Storage Overflow
8	2	1

Survey Q8 Wade Hall

Requires Major Capital Funding to Deliver

	Update Kitchen	Complete Remodel / Upgrade	Repaint	Improve Lighting	Improve Sound and AV System	Replace Flooring	New Drinking Fountain	Redo Stage Area	Create Outside Courtyar
Cosmetic painting, move Supper club storage			1						
to another area. Improved lighting and sound system. Kitchen needs to be updated and expanded.	1			1	1				
Refresh flooring, adjustable lighting, paint			1	1		1			
Add new(or repair) drinking fountain.							1		
Desperate need for updated, larger and more efficient kitchen.	1								
Update lighting. Make full use of space instead of having part of the room as storage behind the partition				1					
Fresh paint			1						
Definitely needs a face lift! There is so much potential. The kitchen should be a priority. I have seen roaches in the utensil drawers, rust and water, etc	1								
I think it needs updating but I have a bad eye for what would improve. It would be great if it looked like a place one might have a wedding reception or retirement reception and if it had technology so that when we have programs it is easily equipped for AV					1				
repaint			1						
Redo the stage ceiling to take out the drop ceiling and install a metal grid that can support lights and other materials for greater versalility. Like halls have a regular repainting schedule.			1					1	
feels run down		1							
paint			1						

 our Mark oject(s)

Day Pr	oject(s)
Clean	Address Storage Overflow
	1
	1

Survey Q8 Wade Hall

Requires Major Capital Funding to Deliver

					Improve				
		Complete			Sound		New	Redo	Create
	Update	Remodel /		Improve	and AV	Replace	Drinking	Stage	Outside
	Kitchen	Upgrade	Repaint	Lighting	System	Flooring	Fountain	Area	Courtyard
Replace the sound system; remove the	Kitchch	Opgrade	Керапи	1 Lighting	1	1 looring	1 Ountain		1
columns and dated partitions to allow for more		1		1	1			1	1
light and expand the space (the space the									
partitions block off has never been used for									
anything other than storage). Remove the									
stage to enlarge the room. Enlarge the open									
space where plates are passed (on Wednesday									
nights) to a larger window and/or create a									
serving space there in place of the tables in									
front of the stage. Renovate/update the kitchen.									
Create access to the Breakfast Club pantry									
through the kitchen wall instead of the door									
from the fellowship hall itself (or turn the									
Breakfast Club closet into a large walk-in,									
restaurant style refrigerator/freezer).									
Reconfigure the playground so that part of it									
can be used as a courtyard more easily									
accessible from Wade Hall. An open air									
courtyard would provide a nice space for small									
events (welcoming new members, Easter									
Kitchen needs replacement of gas and possibly	1								
dishwasher									
Not a priority at this time. Kitchen could use a	1								
lot of improvement.									
Replacement of the windows, as needed.	1	1							
Complete redo of the kitchen, considering the									
plans from several years ago to move it to the									
other side of Wade Hall.									
working water fountains (not during Covid)							1		
This space could be updated easily with	1		1						
scheduled painting and cleaning as needed. It's									
a great space. I'm sure kitchen are may need									
some updates with appliances, counters, etc									
that would help with community ministries. Get rid of accordion doors, replace floors,	1	1				1			
repaint with new color, gut the kitchen and	1	1				1			
modernize with new equipment									
Upgrade		1							
Update		1							
Rework the entire hall. Very poor use of space.		1							
Extend existing storage room to store needed		1							
items.		1							
Updating kitchen and pantry to include hvac,	1								
plumbing, and appliances (except new oven).									

Make Your Mark Day Project(s)											
Clean	Address Storage Overflow										
1											
	Page										

Survey Q8 Wade Hall Make Your Mark **Requires Major Capital Funding to Deliver** Day Project(s) Improve Complete Sound New Redo Address Create Remodel Drinking Update Improve and AV Replace Stage Outside Storage Kitchen Upgrade Repaint Lighting System Flooring Fountain Courtyard Clean Overflow Area Complete renovation of the kitchen Kitchen needs updates and cleaning, Need to lighting and paint personally would like to see a different type of 1 flooring in there. The parquet dates the space. It feels dated but really I think a fresh paint 1 color would go a really long way here. This needs an overall renovation to modernize this space. This needs to have an updated integrated audio and video system installed - the current set up is archaic and virtually useless. We could have much more flexibility for ministry in this space if renovated to account for actually having services or events in this space that would used audio and video as part of the ministry. The floor needs to be replaced and modernized. The stage could be removed or renovated to make it more useful - a backdrop other than blackout paint should be installed and the curtains removed. The paint needs upgrading throughout Wade Hall as well as the lighting to make it more inviting. The kitchen could use some renovations to things like drainage (the grease trap tends to flood the space at times). The old refrigerators in the pantry should be disposed of and replaced with fine for what it is Storage for stage and side areas need to be provide so Wade Hall can be a dinning space totally or large meeting space repair parquet, repaint Could use if nothing else a serious

technology overhaul.

Survey Q8 Wade Hall Make Your Mark **Requires Major Capital Funding to Deliver** Day Project(s) Improve Complete Sound New Redo Create Address Drinking Update Remodel Replace Outside Improve and AV Stage Storage Kitchen Upgrade Repaint Lighting System Flooring Fountain Area Courtvard Clean Overflow Wade Hall needs to be painted BADLY. The yellow color is old and ugly. Additionally, the room needs to be fully opened and all the miscellaneous items being stored behind the partition need to find a new home. The sound system needs to be updated so this can truly be a proper a little updating ... kitchen may need some Good Fresh paint. Hall itself is sufficient, but kitchen needs gut revamp. rennovate sink in kitchen - draining issues, low height 1 puts stress on people's back It is not very attractive and is very dark; the flooring is bad and the stage is ugly. It's really dated looking. White hall as well as the kitchen could use a complete overhaul. The flooring needs to be replaced update the kitchen to a more modern appliances and give the stage a Kitchen remove non functioning equipment, 1 Clean as needed RE-do completely- add technology for presentations and live studio type casts; paint all per above - possibly move offices Improve/increase seating Improve appearance (updated flooring) 17 **Totals** 15 12 5 7 8 2 4 4

Survey Q9 Chapel interior Make Your Mark **Requires Major Capital Funding to Deliver** Day Project(s) Deep Clean New Remove Address Replace Plaster Improve Pews / Chancel Stained Glass Add Storage Flooring Artwork Overflow Repair Lighting Upgrade Repaint Fix Leaks Chairs **Furniture** Windows Clean Patch plaster, repaint. Replace Repair the floor, better lighting, 1 painted Flooring is bad. 1 Add tile flooring that has been discussed by the trustees for several years Refinish floors new paint Complete the remodel job that was started years ago. New flooring, new pews or nice chairs/seating How could we make this a more used space? I like how it is used for intentional spiritual growth activities during Advent and Lent. I also like using it for Wednesday night spiritual I would restore it to its original layout and use it for small weddinas. While the cork flooring is 1 absolutely period appropriate and wonderful, removing pews left holes in the floor. Time to replace the cork tiles. Fix the leaks. Install a retrofit or new floor to accommodate flexible sesting. Upgrade lights so people can actually see in evening events. last time I was in there the 1 flooring was messed up. update flooring

	Survey Q9 Chapel interior													
	Requires Major Capital Funding to Deliver											Make Your Mark Day Project(s)		
	Replace Flooring	Plaster Repair	Improve Lighting	Upgrade	Repaint	Fix Leaks	New Pews / Chairs	Remove Chancel Furniture	Deep Clean Stained Glass Windows	Add Artwork	Clea		Address Storage Overflow	
Install hardwood flooring. Update lighting. The seating in a circle seems to work well in the space but more updated seating is needed. Repaint. Make better use of the wall space by displaying artwork, banners, etc. Can any of the chancel furniture be removed to open up the space? Flooring replaced.	1	•	1	15	1			1		1				
Fix plaster and ceiling. New floor in keeping with original. Cosmetic maintenance.	1	1												
Not sure about the flooring in there - at one point I believe it was partially pulled up	1													
Redo the Chapel floor.	1													
Chapel flooring needs to be replaced, deep clean stained glass windows & lighter interior I'm still sad that the pews were	1				1				1					
removed. It has lost its character and purpose in my fix the roof/ ceiling, replace	1	1				1								
floor. Is the Chapel used? Can we rent/ loan it to another church or other purpose?	-	_												
Decide how we want to use that space. It appears to be something we don't know what to do with - and once we decide, support it with how the interior is set up. It feels crowded and an afterthought														
UUUPPP GGRRAADDEE BAD				1										

	Survey Q9 Chapel interior													
	Requires Major Capital Funding to Deliver											Make Your Mark Day Project(s)		
	Replace	Plaster	Improve				New Pews /	Remove Chancel	Deep Clean Stained Glass	Add			Address Storage	
	Flooring	Repair	Lighting	Upgrade	Repaint	Fix Leaks	Chairs	Furniture	Windows	Artwork		Clean	Overflow	
Very outdated, severe in appearance and not at all comfortable or welcoming to participants; this is probably an		•		1	1									
area to consider for gutting and complete modernization. Large windows facing out to Peachtree St. would be a more														
welcoming face for visitors and Update				1							lŀ			
Modernize it. Very old!!				1										
complete flooring to be all slate, repair leak in roof? repair damage	1	1		1		1								
Repair needed, make have an even older world feel		1												
adorable, needs new lighting and finally please fix the floor This could use some brighter	1		1								-			
lighting. I never really knew what was	1										-			
going on with the floor here. Hire (or find someone to donate their time) a historical architect /decorator for help here.											-			
Time for the floor to be completed. The modular seating is a great plus to how	1													
this space can be used rather than traditional pews!														
Could we replace/update the floor	1													
it's nice as it is											l			
One solid flooring please and refinish of all wood work. Brighter lighting	1		1									1		

	Survey Q9 Chapel interior											
			Req	uires M	ajor Ca	pital Fu	nding t	o Delive	er			Your Mark Project(s)
	Replace	Plaster	Improve				New Pews /	Remove Chancel	Deep Clean Stained Glass	Add		Address Storage
	Flooring	Repair	Lighting	Upgrade	Repaint	Fix Leaks	Chairs	Furniture	Windows	Artwork	Clear	Overflow
replace floor (I vote for a	1	1	1		-							
light beige color), add more												
lighting, repair plaster,												
replace missing ceiling panels												
Floor finally being finished.	1		1			1						
Roof issues. Could also use												
some lighting upgrades, its a												
beautiful space and could be												
much more versatile if more												
lighting were there (could be												
space for art installations,												
stations of the cross												
meditations, etc.)												
Needs new flooring.	1											
Committee just needs to												
finally decide. Love the												
versatility of the space.												
Redo the floors	1											
return pews							1					
Good												
Repair wall damage from	1	1			1							
water leaks including the												
ceiling tiles. Fresh paint.												
New floor.												
Fine except ceiling and floor.	1	1										
put pews back in, update							1					
replacement of floor covering	1											
The chapel is really cute;			1									
perhaps additional lighting in												
there would be helpful.												
Fix floors	1											
Cleaning per COVID											1	

	Survey Q9 Chapel interior												
		Requires Major Capital Funding to Deliver											our Mark oject(s)
							New	Remove	Deep Clean				Address
	Replace	Plaster	Improve				Pews /	Chancel	Stained Glass	Add			Storage
	Flooring	Repair	Lighting	Upgrade	Repaint	Fix Leaks	Chairs	Furniture	Windows	Artwork		Clean	Overflow
Update new floor, fix leaks,	1		1			1							
update lighting. Rework													
interior wall in corridor													
around the chapel - s=custom													
graphics to mimic exterior -													
add fin programming info in													
windows.													
The floor needs to be restored	1] [_	
Totals	32	8	10	4	4	5	4	1	1	1		2	0

	Survey Q10 Parlor/Brides room areas														
					Requ	ires Maj	or Capi	tal Fun	ding to D	eliver					Mal
	Update Furniture		Upgrade Bathroom	New Flooring	Upgrade Lighting	Major Renovation	Repair / Replace Windows	Update Artwork	Update Window Treatments	Remove Piano	Rename to Gender Neutral	AV Connections to Santuary	Fix A/C	Add Electrical Outlets	Clean
Parlor should remain same location. Rearrange all the remaining areas for single stall gender	1 41111411	unen	1	Treering	2.55		W III GOW	7 220 11 0222		T AMITO	T (Outro)	Suntum	111120		Citani
neutral restrooms															
Refresh with new flooring, paint and lighting				1	1										
repair or replace windows							1								
New carpet and paint				1											•
Just a cosmetic update would be nice		1													
Updated furniture and paint. Maybe not labelling this as brides room, but giving it a name of a donor and Parlor. This way all genders of wedding participants	1										1				
are included AND we could use it as a speaker ready room for events etc.															
I think all the rooms need a facelift and new furniture	1	1					<u> </u>					<u> </u>			
Since this is a financial draw, we may need to spruce up the area a bit	1	1													
restrooms feel dated			1												
new furniture	1														
Create a designated space in the parlor (or along the wall that connects to the Education building) to display some of our wonderful historical photos including the panoramas that everyone loves to see at Homecoming. Replace light fixtures. Remove the small piano that is decorative but not functional. Update the furniture and window treatments. Add electrical outlets near the counter in the bride's room. Add a small refrigerator where the desk currently is in the bride's dressing room (large enough for ice and for the florist to store bouquets, etc.) The parlor is a better, larger, and more comfortable space than the old bride's room to offer to parents with infants or toddlers but we would need to add AV equipment so they could continue to watch/listen to worship if they	1				1	1		1	1	1		1		1	
Parlor. Just neaten it up. Bride room. Renovate						1									
completely. Update and redo the bathroom completely.			-1								ļ			├ ──┤	
			l				1				-			├──┤ ├	
Replace all windows, some of which have started to	1			1	-		I				-	-		├──┤ ├	
Complete renovation with updated furniture/lighting/flooring Consider updating carpeting and furnishings as	1			1	1									<u> </u>	
needed without losing the timeless character of the	1			1											
Complete overhaul. Weddings are/ should be an income generator. New flooring, wallcovering, window treatments, and furniture	1			1				1	1						
Restrooms need major renovation			1												
Upgrade			1											<u> </u>	

Make Your Mark Day Project(s)

	Make	Your Mar	K Day 110	jeci(s)
1		Update	. 11	
		Floral	Add	
	Clean	ents	Refrigerat or	Repaint
1		51115	- 01	repuiii
-				1
-				1
				1
-				
			1	
1				
1				
1				
-				
1				
1			Page 39	
_				

		Survey Q10 Parlor/Brides room areas																
					Requ	ires Maj	or Capi	tal Fun	ding to D	eliver					Make	Your Ma	rk Day Proj	ject(s)
	Update Furniture		Upgrade Bathroom	New Flooring	Upgrade Lighting	Major Renovation	Repair / Replace Windows	Update Artwork	Update Window Treatments	Remove Piano		AV Connections to Santuary	Fix A/C	Add Electrical Outlets	Clean	Update Floral Arrangem ents	Add Refrigerat or	Repaint
Update		1										,						<u>F</u>
Small much too small		1				1								1		 	 	
reupholster older dirty furniture or redo entire room to more contempory look??	1	1																
update floral arrangements		1														1		
Please please bring these rooms into this century, poor look for weddings These are ok. The a/c unit in the bride's room needs		1											1			<u> </u>		
to be fixed.																		
Paint, new light fixtures, update funiture.	1				1													1
The parlor needs to be modernized and outdated furniture removed. It is not inviting as a parlor -	1	1																
that says dated and old rather than welcoming. A living room or lounge would be a better use of																		
this space especially as a gathering place for																		
between services - like a welcome center with																		
coffee and information about the church. The																		
brides room should be eliminated and could be																		
used either to expand and renovate the bathrooms																		
or to expand the living room. Given the limited																		
number of weddings at the church and the trends																		
away from weddings in churches it seems like a																		
waste of space to earmark that for something that																		
doesn't happen often. Brides can be																		
accommodated in another location in the church if																		
no opinion																<u> </u>		
Transform the Parlor to a Gathering space for coffee/juice on etc on Sundays. Change the Brides		1									1							
room to the Wedding Preparation Suite																		
new carpet, better lighting				1	1													
Needs to be updated. The piano in that space is untunable and serves no purpose. We should use that		1								1								
space for coffee/welcome room.																		
fine as is																		
Good																		
Fix windows from water damage. Fresh paint							1									1		1
Fine but utilized optimally?																		
renovate					1	1												
Update/upgrade		1														t	† ***	
Ok		1														$\overline{}$	\vdash	
If needed, clean drapes and furniture, and															1	$\overline{}$		
, 1	1	1	1		1	1	1	1	1	1	1	1			-		Page 40	1

	Survey Q10 Parlor/Brides room areas													
	Requires Major Capital Funding to Deliver													
		Cosmetic Updates /					Repair /		Update		Rename	AV Connectio		Add
	Update Furniture	Moderniz	Upgrade Bathroom	New Flooring	Upgrade Lighting	Major Renovation	Replace	Update Artwork	Window Treatments	Remove Piano	to Gender Neutral	ns to Santuary	Fix A/C	Electrical Outlets
Repurpose this entire area - open top to corridor and dxtedn to Peachtree with glass. Cube/ red doors - use as a tru narthex, meet and greet, area where we provide coffee. Seasonally have area to sell fundraising materials						1						·		
Seems like wasted space, but there may be uses for it of which I am not aware.														
Totals	10	10	5	6	5	5	3	2	2	2	2	1	1	1

Make	Your Mar	K Day Pro	ject(s)
	Update		
	Floral	Add	
	Arrangem	Refrigerat	
Clean	ents	or	Repaint
1	1	1	4

Survey Q11 New bridge between new parking deck and building

				u Dunum	5				
	Requir	es Major	Capital F	unding to		Make Yo	ur Mark		
	1	-	eliver		Day Project(s)				
	Create	Not an							
	Covered	Option -							
			Tanker-1-	Enlly ADA					
	Main	Must	Technolog	Fully ADA		G1	ъ .		
	Entrance	Have	y Capable	Accessible		Clean	Repaint		
Covered. Attractive door at each end. This	1								
will become our main entrance.									
Not an option must have		1							
Construct bridge, covered/climate	1								
Make it decorative, well-lighted and	1				1				
secure, plus protect d against the elem									
looks nice	1								
YES!	1								
Is it open air or covered and temp	1								
regulated?									
Making sure it is fully handicapped				1					
accessible									
Handicap accessible, lots of light				1					
It should have welcoming architectural	1				1				
style, not just utilitarian. It is the first thing									
most people will see. Probably should be									
enclosed so you step from deck into a									
warm, welcoming space.u									
light it well and ensure security	1								
Well lit, secure, and temperature	1				1				
regulated. The walkway from Peachtree	-								
Center to some of the nearby hotels									
COnsider its role as point of access and	1								
whether reception should be here.									
Make it in keeping with the historical	1								
character of the 1903 building.									
Appropriate lighting, easy but secure	1								
access. Once entering the bldg from the bridge	1								
convert some of the classrooms to make a	1								
greeting lobby.									
Covered (not-open air), heated & cooled	1				1				
with controlled access	1								
I'm not familiar with the intended	1								
connection but entrance should be	•								
covered if not enclosed between the deck									
and the building.									
Welcoming, more than utilitarian	1								
Upgrade	1								

Survey Q11 New bridge between new parking deck and building

	Requir	<mark>es Major</mark>	Capital F	unding to		Make Your Mark			
		D	eliver			Day Project(s			
	Create	Not an							
	Covered	Option -							
	Main	Must	Technolog	Fully ADA					
	Entrance	Have	y Capable	Accessible		Clean	Repair		
Yes	1								
This will be an advantage to access to	1				1				
the building. It would be helpful to									
relocate the office space for staff to this									
hopefully handicapped accessible and				1					
well lit									
Well lite and secure. The second floor	1								
becomes the main entrance to the									
church facility and should be									
welcoming and friendly. I would like to									
move the Church Offices to the rooms									
on the right and left as you come in to									
be the first welcome to all									
Should be fully ADA accessible and	1			1					
should lead people by church offices on									
the way to the sanctuary.									
not needed									
Excellent	1								
Make open and welcoming	1								
No comment.									
indoor type with windows protected	1								
from elements									
This should be covered and somewhat	1								
sheltered to help people stay dry									
walking from the deck to the building.					lL				
Very needed	1				l L				
NA					l L				
In process - would like to see monitors -	1		1						
landscape on posts here and at main									
entries to provide a directory -									
interactive even petter to show map,									
display class info, updates on									
programs, fund drives, missions, etc					l L				
Second. When the new parking	1								
structure is built this will be important.					1 L				
sounds great	1				J L				

Survey Q11 New bridge between new parking deck and building

	Requires Major Capital Funding to								
	Deliver								
	Create	Not an							
	Covered	Option -							
	Main	Must	Technolog	Fully ADA					
	Entrance	Have	y Capable	Accessible					
YEScovered and climate controlled	1								
with excellent signage									
Totals	30	1	1	4					

Make Your Mark Day Project(s)									
Clean	Repaint								
0	0								

	Survey Q12 Restrooms in education buildings											
		Major Ca				our Mark						
	Requires	-		unig to		oject(s)						
		Delive			2 uj 11	J						
	Modernize /	Total	Cosmetic	Plumbing								
	Update	Renovation	Updates	Upgrades	Clean	Repaint						
Eliminate entirely, replace with new		1										
restrooms in brides room area.												
Need updating	1											
Up dated. The busiest restroom is the	1											
smallest												
Replace toilets w low water use units,	1											
save a ton on water bills and flush												
Environmentally friendly. Bathrooms	1											
could use updating with no water												
urinals and toilets with dual flush and												
turn on hot water Cosmetic updates would be nice			1									
-	1		1									
They need to be overhauled and modernized with new fixtures and	1											
Update to ensure working fixtures.	1											
Perhaps convert all to unisex like on the												
2nd floor												
all restrooms need updating. maybe	1											
install electric hand dryers also. better	1											
lighting in some of the restrooms												
Updated and new paint	1											
All need some maintenance.	1											
complete remodel and update, redo	-	1										
plumbing		1										
Great to have all gender. Do we have	1			1								
showers in those that are near the	1			1								
gym? Do we need to update those on												
the childrens hall? They have those tiny												
potties and I think are pretty old.												
Fix the plumbing and upgrade the	1			1								
restrooms (sinks, toilets, doors, paint,												
etc.)												
BIG PROBLEM. I don't mind that our				1								
restrooms look like they were original to the construction, but plumbing												
continues to be an issue. Education												
Building Third Floor restrooms have an												
odor coming from the pipes that seems												
to be a constant problem												
Update the plumbing. Keep the				1								
attractive basket weave tile if possible.												
But yhe plumbing in the whole building												
needs upgrading.												
update and paint	1		1									
All need a complete overhaul. Ideally	1											
offer diaper changing stations in each.												

	Surve	y Q12 Res	trooms	in educa	ti <u>on</u> buile	dings
		Major Cap Delive	oital Fun		Make Yo	our Mark oject(s)
	Modernize /	Total	Cosmetic	Plumbing		
	Update	Renovation	Updates	Upgrades	Clean	Repaint
All need to be re-done. Potentially	1	1	1	18		1
consolidate location and type of RR		-				
Neaten them up. Get plumbing in good			1	1		
repair.						
GONE. These are all abysmal and need		1				
to be redone completely.	1					
Foundation's class, maybe doors on the	1					
stalls with the little toilets						
Update all restrooms	1					
Bathrooms need to be renovated	1					
These need to be updated and	1					
modernized	1					
Gutted and brought up to code.		1				
Upgrade	1	<u> </u>				
In poor shape and desperately in need	1					
of modernization	1					
These need renovation!	1					
Update	1					
repaint, restore, restrooms	1					
They need to be modernized and	1	1				
perhaps expanded?	1	1				
Total renovations all bathrooms all		1				
These need to be updated. They are	1					
old and dark.						
While they are pretty historic and quirky	1					
they also could stand updated fixtures						
if they can be updated without reducing						
the number of available stalls. Time for them to be updated.	1					
•						
definitely could use updating	1					
New restrooms all together or		1		1		
modernize please. Pipes updated to						
provide clean drinking water						
replace most of them with a		1				
bathroom stack						
Again, overhaul, gender neutral		1			_	
More ADA-friendly/parent-	1					
friendly/non-binary-friendly single-						
stall restrooms that actually lock with						
proper water pressure and flush.						
All restrooms are in need	1					
fine as is	1					
11110 48 18						

	Surve	y Q12 Res	trooms	in educa	tion buil	dings
	Requires	s Major Ca Delive	-	ding to		our Mark roject(s)
	Modernize / Update	Total Renovation	Cosmetic Updates	Plumbing Upgrades	Clean	Repaint
Good						
Gut, update all bathrooms with new		1		1		
fixtures and low flow toilets. New						
floors, fresh paint						
See restroom comments above. Many plumbing issues in this				1		
renovate	1					
need renovation/replacement	1					
Need to be updated for sure.	1					
Definitely upgrade. Men's room	1					
especially could be enlarged. I've						
never been in the ladies so I don't						
know.						
Completely renovated		1				
Complete remodel		1				
Ahtotal upgrade		1				
Restrooms need to be totally		1				
renovated						
Update	1					
Need upgrade	1					
complete overhall		1				
Children's floor needs dramatic		1				
renovation						
Total	35	17	3	8	0	0

						Survey	Q13 Gy	mnasium	/Drama	theatr	e				
					Require	s Major (Capital F	unding to l	Deliver						Your Mark Project(s)
	Create Multi-Use Facility	Cosmetic Updates	Major Updates	Improve HVAC	Improve or Reduce Storage Dependency	Fix Roof Leaks	-	Improve Drama Capabilities	Add Stadium Seating	Paint	Improve AV Capabilities	Remove Drop Ceiling	Improve Lighting	Clean	Repaint
Up grade as a better multi use facility	1	орашев	оринев	11 / 110	Bependency	Leans	Ticoring	Сириоттись	Seating	T unit	Сириоттись	coming	Digitting	Cicun	Терине
Better Heating/AC. Upgraded lighting and pole supports on ceiling for theatre backdrops and curtains and scenery Cosmetic updates would be nice	1	1		1				1					1		
Replace flooring add stadium seats to allow for more use as a theater space and also as a community gymnasium with events such as basketball and volleyball	1	1					1		1						
ok but needs sprucing up Updated with new paint and equipment to draw more youth - but ask them! Again, cosmetic updates to make it a more inviting		1 1													
space. Would be great to upgrade the AV capabilities in this space and to have it as a reservable space for community events	1										1				
Need storage areas cleaned and provided so that gym can be used as a gym and not storage Install HVAC but esp AC adequate to the space	1			1	1	1	1			1		1			
(events in summer are currently almost impossible due to inadequate AC).Permanently fix leaky roof. Remove popcorn drop ceiling, paint black and install a metal grid from which lights, flats, and other articles can be hung to make the room truely multipurpose and functional as a reslly good theater and performance and recrestion space. Make sure floor surface is comfortable and															
appropriate for sports but resists scuff, wear and damage from street shoes. We have to put down protetive plywood any time there is a dance, play. Or audience requiring chairs to protect current															
paint Turn the current closet into an AV booth for drama productions. Improve lighting. Add a light switch to turn on the lights (currently you have to flip breakers to turn on the lights). Reconfigure so that half the space is a gym and half is a permanent, black box theater space. Or install fold up bleacher style seating along the walls for drama productions	1							1	1	1					
Better lighting and storage for material, equipment, chairs					1										Page 48

						Survey	Q13 Gy	mnasium	/Drama	theatr	e				
					Require	s Maior (Canital F	unding to l	Deliver						our Mark
					-	3 Ivingor (supitui i	unuing to i						Day P	roject(s)
	Create Multi-Use Facility	Cosmetic Updates	Major Updates	Improve HVAC	Improve or Reduce Storage Dependency	Fix Roof Leaks	Replace Flooring	Improve Drama Capabilities	Add Stadium Seating	Paint	Improve AV Capabilities	Remove Drop Ceiling	Improve Lighting	Clean	Repaint
New roof, new or repaired HVAC.	raciity	Opuaics	Opuaics	1 1 1	Dependency	1	Tioornig	Capaomitics	Scatting	1 ann	Capaointies	Cennig	Lighting	Cican	Керапп
Update as needed based on likely use going		1		1		1									
Gym always looks so messy and unkept - maybe a		1												1	
storage area for balls, etc. Turned into a sanctuary for a contemporary service option like the 1st UMC Birmingham														1	
Upgrade			1												
In poor shape and desperately in need of modernization Update			1												<u> </u>
Drama closest in gym moved or changed to gym storage			-		1										
If it's not utilized it should be converted to spaces															
that would. The drama ministry has been less effective than	1				1	1									
other ministries at reaching out to people in the	1				1	1									
community and making disciples of Jesus															
Christ. I would suggest removal and disposal															
of all drama related materials. If there was an															
outside group that wanted to contract with us to															
use the space to put on their production we															
could work with them to rent the space at that															
point. I would love to see the gym updated so															
that our youth and children can use this space															
safely. Also this space has the potential to be															
used for community engagement for something															
like pickup basketball for those in the															
stop water leaks in roof. As far as theater, it is what it is.						1									
Restore the Gym for youth and athletic use.	1														
Find a space for Drama when we have this															
ministry again															
cleaned up														1	
Leaks in the gym roof MUST be addressed!					1	1									
Drama needs to be relegated to fewer storage															
spaces. We don't have much drama anymore															
(compared to my understanding of years past)															
and yet, there's drama storage absolutely															
everywhere.															Page 49

						Survey	Q13 Gy	mnasium	/Drama	theatr	e				
					Requires	s Major (Capital F	unding to l	Deliver						our Mark oject(s)
	Create Multi-Use Facility	Cosmetic Updates	Major Updates	Improve HVAC	Improve or Reduce Storage Dependency	Fix Roof Leaks		Improve Drama Capabilities	Add Stadium Seating	Paint	Improve AV Capabilities	Remove Drop Ceiling	Improve Lighting	Clean	Repaint
fine as is															
Good															
New lights, ceiling from water damage. Fresh						1							1		1
paint															
Total Reno needed.			1												
renovate			1												
repair of leaking roof, a/c struggles to cool						1					1				
I don't know were to begin.															
state of the art gymnasium			1												
Sort and disposed of worn out supplies, drapes, junk					1										
Upon funding - create tru Drams dept area. Stage - (wade hall ?) and sperate Gyp/multi- dividable activities areas, and separate Choir area with sound. Tech needs included.								1							
Create black box theatre								1							
Totals	8	5	6	3	6	7	2	4	2	2	2	1	2	2	1

			Survey	Q14 Ed	ucation	buildir	gs, thir	d floor,	other tl	nan the	gym. (Youth a	nd Mus	ic suite,	offices)		
					Red	quires N	Aajor C	apital F	unding	to Deli	ver						our Mark roject(s)
	Major Renovatio n	Renovate / Upgrade Bathroom s and Locker Rooms		Cosmetic	Updates	New Carpeting	Upgrade Electrical & Plumbing	Improve HVAC	Relocate Room Assignme nts to Other Areas	Update Lighting	Youth Items - Pool table, Foosball, etc.	Sound System / Technolog	Repair Lockers	Update Furniture	Update Youth Kitchen	Clean	Repain
Cosmetic. Relocate choir Room to north side (remove walls) to facilitate relocation of rest rooms Complete Re-build, or major renovation of	1 f 1			1								,					
Ed. Bldg. Paint and updating all levels	1				1												1
Make windows operable, Add a speaker system such as a Sonos or other to allow music to be played in the suite for teaching purposes			1		1							1					1
spruce up and maybe new carpeting				1		1											
Updating with new paint																	1
Update lighting in the middle choir room										1							
between the offices and practice room.																	
Jess has made great strides with the Youth suite and with more funding I am sure would have even more improvements to make this appealing to youth. Pool table? Foosball? Somewhere Upgrade electrical and plumbing in the							1				1						
building; Refresh and redo bathrooms, but		1															
otherwise I like it. LLP paint and update furniture														1			1
Update youth kitchen, all restrooms (including locker rooms) and 3rd floor HVAC system. If all the staff offices could somehow be relocated / centralized in the Education building, it would provide more needed classroom and/or storage space		1						1	1					1	1		1
Reassess the showers - do we need them? if not, open portions of that wall, reduce kitchen counter. Whole area could	1	1															
be more of a lobby / gathering space Fix HVAC, Plumbing, Roof, Electrical,			1	1			1	1									
Windows. Cosmetic improvements. Update bathrooms on this floor insure sufficient storage, and replace windows.		1	1														
The restrooms need a face lift - maybe repair lockers and some paint		1											1				1
replace all windows in the education building and choir rooms			1													Pa	ge 51

			Survey	Q14 Ed	ucation	buildin	gs, thir	d floor,	other th	nan the	gym. (Youth a	nd Mus	ic suite,	offices)		
					Rec	quires N	<mark>Iajor C</mark>	apital F	unding	to Deli	ver						our Mark roject(s)
	Major Renovatio	Renovate / Upgrade Bathroom s and Locker				New Carpeting	Upgrade Electrical &	Improve	Relocate Room Assignme nts to Other	Update	Youth Items - Pool table, Foosball,	Sound System / Technolog	Repair	Update	Update Youth		
	n	Rooms	t	Cosmetic	Updates		Plumbing	_	Areas	Lighting		у	Lockers	Furniture	Kitchen	Clean	Repaint
Complete renovation	1																
Gutted and reconfigured.New carpet & Paint (new color), new flooring in hallways Upgrade	1				1	1											1
Update					1												
Youth room moved to another area and room becomes drama room, drama sewing room, prop storage and construction storage. Those former rooms moved from the basement and					1				1								
The youth area is great but I'd like to see all classrooms upgraded with SmartTVs and better technology. The						1						1					
flooring needs to be modernized in the hallways throughout the education fine																	
Modernize this space with good technology and current youth furnishings. Robing closets for robes and fresh paint and carpet for the						1					1	1					
replace carpets (leave Josh's alone; it's new); new bathroom stack can be shortened 8' to leave choir room intact, children's choir room will be moved to 1st floor, replace gym bathrooms,						1									1		
replace youth kitchen new paint maybe new floors. Future smart technology in choir room could be setup to record rehearsals etc.						1						1					1
Music suite should be outfitted with quality recording equipment for Jonathan and the choir/bells to use. Youth space looks nice after recent renovations/updates. I'm sure it could be further updated with proper funds.												1					
fine as is																Pa	ge 52

			Survey	Q14 Ed	ucation	buildin	gs, thir	d floor,	other th	nan the	gym. (Youth ar	nd Mus	ic suite,	offices)		
					Red	quires N	Iajor C	apital F	unding	to Deliv	ver						our Mark oject(s)
		Renovate / Upgrade					T.T. 1		Relocate Room		Youth Items -	G 1					
	Major Renovatio	Bathroom s and Locker	Window Repairs / Replacemen			New Carpeting	Upgrade Electrical &	Improve	Assignme nts to Other	Update	Pool table, Foosball,	Sound System / Technolog	Repair	Update	Update Youth		
	n	Rooms	t		Updates		Plumbing	-	Areas	Lighting	etc.	у	Lockers	Furniture	Kitchen	Clean	Repaint
Good																	
Fresh paint, carpet. New HVAC equip						1		1									1
No comment.																	
rennovate but mostly keep layout					1												
These need to be updated.					1												
Add kitchen(ette)					1												
Clean per PROVID protocol																1	
Update for now paint and update -					1							1					1
add tech as needed for programs and																	1
youth engagement.																	
Totals	6	5	4	3	7	7	2	3	2	1	2	6	1	1	2	1	8

	Survey Q15 Education building, second floor (Peachtree level/Sanctuary level)																		
						Requ	ires Ma	ijor Capit	al Fund	ing to D	Peliver							Your Ma Project(s)	_
	Cosmetic Improve ments	New Carpet / Flooring		Plumbing Ungrades	Major Renovation	Window Repairs / Replacem ents	HVAC Replacem ents		New Seating /	Upgrade Electrical	New Parking Entry Welcome Area	Upgrade Bathrooms	Improve Technolog y Capabilitie s	Upgrade Classroom Counters / Sinks	Remove Hallway Tile	Remove Unneeded Items	Clean	Stained Glass Window Display	Repaint
Welcome room at new parking lot	ments	Tiooning	Lighting	Opgrades	Renovation	Citis	CIIIS	1	Turriture	Licettical	1	Datinoonis		Siliks	THE	Items	Cican	Display	Керапіі
entrance. Turn every classroom on this level to generic conference rooms that Sunday School classes will use, but will not be for their exclusive use. Limit classes to what they may do to											•								
Upgrade restrooms, better hallway lighting, window treatment, update electrical systems for modern			1	1					1	1		1							
electronics and audio visual equipment, new seating , repair plumbing in Complete Re-build, or major renovation					1														
of Ed. Bldg Update lighting, make windows			1			1													
painting and carpeting		1																	1
Updating with new paint																			1
Upgrade electrical and plumbing in the building;				1						1									
Since the HVAC systems (big green units) are original to 1956 we have been living on borrowed time for years. So they should probably be replaced with a more efficient system though it'll never last the 65 years the current equipment has (omitting the off							1												
paint																			1
move the stained glass window display closer to the sanctuary; remove the pews from the hallway outside the parlor. How will the space currently occupied by StreetLights be used once the high rise is completed? Remove the outdated and nonfunctioning counters and sinks (and wall cabinets) in all the classrooms. Also remove all of the old non-functioning pianos scattered throughout the classrooms. We need to streamline and get rid of anything outdated and unused that takes up precious space. Saint Mark is an old church but we can still do a lot to This will be primary circulation. Redo all finishes. Consider selective demolition of walls for windows into rooms or at least glass doors into rooms.					1				1					1		1		1	
Fix HVAC, Plumbing, Roof, Electrical,	1			1		1	1											Page 54	
Windows. Cosmetic improvements.	<u> </u>																	3 -	

				Survey	y Q15 Ed	ucation	buildin	g, second	floor (Peachtr	ee level	/Sanctua	ry level))				
						Requ	ires Ma	ijor Capit	al Fund	ling to I	Deliver						Your Mar Project(s)	•
	Cosmetic Improve ments	New Carpet / Flooring		Plumbing Upgrades	Major Renovation	Window Repairs / Replacem ents	HVAC	Create Multipurpose classrooms / conference rooms	New Seating / Furniture		New Parking Entry Welcome Area	Upgrade Bathrooms	Improve Technolog y Capabilitie	Classroom	Remove Hallway Tile	Clean	Stained Glass Window Display	
Replace windows as needed.						1												1
Complete renovation					1													
new carpet & paint (new color) new flooring in hallways, get rid of the tile in the hallways		1													1			1
Upgrade	1																	
Okay, but probably could use some updating Update	1																	
All rooms upgraded and renovated with more multipurpose function. Movable walls etc. More technology. Proper air conditioning	1						1	1					1					
These could use some repair, fresh paint, and new carpet or LVT flooring.		1																1
The education rooms really could all use some updated paint colors, window treatments carpet and light fixtures. The hallway really could use a bit better lighting.		1	1															1
In need of a facelift - the flooring needs to be upgraded, lighting needs to be assessed, windows need to be examined for functionality and for energy efficiency. Classrooms need to be outfitted with SmartTvs and proper technology. All bulletin boards in hallways should be removed and consider replacing with monitors that can be used to share information. This is the floor where the main entrance will be from our parking so the administrative offices should be close to the entrance. It would be nice if this could also be connected to street access at		1	1			1					1	1	1					
ok, but definitely need to update bathrooms, especially the one right outside the Interactions classroom. Very cramped.												1						

				Survey	v Q15 Ed	ucation	buildin	g, second	floor (l	Peachtr	ee level/	/Sanctua	ry level)						
						Requ	ires Ma	ijor Capit	al Fund	ing to I	Peliver		,					Your Ma Project(s)	
						**** 1		Create			New		Improve	77 1					
	Cosmetic	New				Window Repairs /		Multipurpose classrooms /	New		Parking Entry		Technolog v	Upgrade Classroom	Remove	Remove		Stained Glass	
	Improve	Carpet /	Upgrade	Plumbing	Major		Replacem	conference		Upgrade	Welcome	Upgrade	Capabilitie	Counters /	Hallway	Unneeded		Window	
	ments				Renovation		ents	rooms	Furniture			Bathrooms		Sinks	Tile	Items	Clean	Display	Repaint
This becomes the main entrance		1									1								
through the parking deck and the																			1
Peachtree Street entrance. All new																			1
carpet/paint/furnishings and																			1
technology for education. Perhaps																			1
another large space with doors into a																			1
garden behind the chapel (fenced in																			1
with benches)																			1
replace all carpet, modify all	1	1																	
classrooms to have built-in closets																			1
New paint and flooring		1																	1
Fresh coat of paint and new carpet is		1											1						1
necessary! Properly outfit all the																			1
classrooms with technology so that																			1
any staff member or guest speaker																			1
could easily wire into a TV for																			1
presentations or to show clips.																			1
Additionally, all classrooms should																			1
be fitted with some sort of device so																			1
that people who have become																			1
accustom to Zoom-ing into Sunday																			1
School have that option post-																			1
fien as is																			
Good																			
Fresh paint, carpet, shelving. Add		1					1						1						1
wifi to all rooms. New HVAC equip		1											1						l [*]
Needs sprucing up and evaluation of	1																		
optimal use.	1																		1
see #14																			
Upgrade, remodel,	1																		
The HVAC does not work well in	1		 				1												
winter we can freeze, in summer we							1												1
are roasting.																			1
Clean per COVID protocol																	1		<u> </u>
Blow out - enhance connection to			†								1	1					1		
parking - possible add offices here -											1	1							1
few large classrooms. Large																			1
restrooms and Large (loose the																			1
Bridal room) open social 'coffee/																			1
beverage communal area.																		Page 56	1
ocverage communar area.	<u> </u>		<u> </u>	<u> </u>		<u> </u>	<u> </u>				<u> </u>	<u> </u>	<u> </u>						

				Survey	Q15 Ed	ucation	buildin	g, second	floor (l	Peachtr	ee level/	Sanctua	ry level)						1
						Requ	ires Ma	ajor Capit	al Fund	ing to D	Peliver							Your Mai Project(s)	•
		Create New Improve Window Multipurpose Parking Technolog Upgrade																	
						Window		Multipurpose			Parking		Technolog	Upgrade				Stained	
	Cosmetic	New				Repairs /	HVAC	classrooms /	New		Entry		y	Classroom	Remove	Remove		Glass	
	Improve	Carpet /	Upgrade	Plumbing	Major	Replacem	Replacem	conference	Seating /	Upgrade	Welcome	Upgrade	Capabilitie	Counters /	Hallway	Unneeded		Window	1
	ments	Flooring	Lighting	Upgrades	Renovation	ents	ents	rooms	Furniture	Electrical	Area	Bathrooms	S	Sinks	Tile	Items	Clean	Display	Repaint
HVAC needs upgrade throughout							1												1
building																			1
Totals	10	10	4	3	3	4	6	2	2	2	4	3	4	1	1	1	1	1	9

					Survey	Q16 Edu	cation bui	lding, fi	rst floor	· (Childre	en's wing)						
						Require	s Major C	apital F	unding	to Delive	r						our Mark oject(s)
	Cosmetic	Major		Replace	Upgrade	AV / Technology	Window	New	Replace						Replace		
	Improvem ents	Renovatio n	Improve Lighting	Carpet / Flooring	Electrical / Plumbing	Security Cameras	Repairs / Replacement	Playgroun d	Ceiling Tiles	Landscapin g	HVAC Improvements	Refurnish	Fix Roof	Improve Security	Access Doors	Clean	Repaint
New playground and entrance direct to first floor.								1									
Complete Re-build, or major renovation of Ed. Bldg		1															
Better lighting in corridors. It is so dark and			1														
painting and carpeting			-	1													1
Updating with new paint				1													1
The Children's wing (particularly the children's		1															
classrooms) need a lot of attention. Projects have		1															1
started but were never completed (mural, room																	1
remodels, etc)																	
Upgrade electrical and plumbing in the building;					1	1			1								1
Foundations classroom needs new carpet, ceiling																1	1
tiles, removal of the partition that is broken, new																	1
paint, installation of cabinet to hold electronic																	1
equipment, would like a wifi camera installed so we																	1
can broadcast class when back in the building paint																	1
Is the second office off of the 'lobby' in the	1									1							1
Children's wing being used for office space or	1									1							1
storage space? Large, archival / library style rolling																	1
shelves in the rooms designated for storage would																	1
better utilize the space. Replace the old wood																	1
cabinets in each Sunday School room (adult																	1
classrooms too) with more updated cabinets.																	1
Remove the old coat/hat racks that are no longer																	1
used. Improve the view from the children's																	1
classrooms on the first floor by planting flowering																	1
shrubs to serve as a screen between the education																	1
New finishes	1																
Fix HVAC, Plumbing, Roof, Electrical, Windows.	1				1		1				1		1			 	\vdash
Cosmetic improvements.					1		1				1		1				[]
Replace windows and access doors, and update	<u> </u>			1			1					1			1	1	
bathrooms. CLEAN the entire place, replace floors							-									1	1
with LVT and refurnish.																	
Check points for adults removing children from														1			
class if applicable-we may have tried that for our																1	
Safe Sanctuary, but maybe it didn't work																<u> </u>	\vdash
Complete renovation		<u>l</u>															\vdash
Gut and configure to code so we can have a		1															
Education rooms need to be clean, appropriately						1										1	[]
appointed, with technology to support all needs					1												\vdash
Upgrade	1																
Okay, but probably could use some updating	1																igwdown
Update	1			<u> </u>													

					Survey	Q16 Edu	cation bui	lding, fi	rst floor	· (Childre	en's wing)						
							s Major C										our Mark oject(s)
	Cosmetic Improvem ents	Major Renovatio n	Improve Lighting	Replace Carpet / Flooring	Electrical /	AV / Technology Security Cameras	Window Repairs / Replacement	New Playgroun d	Replace Ceiling Tiles	Landscapin g	HVAC Improvements	Refurnish	Fix Roof	Improve Security	Replace Access Doors	Clean	Repaint
Seems to be a little dark to me. It could use some more/better lighting. Otherwise, I think Shelia and Jess have done a great job with it. I wish we could put LVT on the floors. It would make it more			1	1													
Really I usually am on the peachtree level more, but I think most of what this needs is similar to the rest new paint, lighting etc This area needs a renovation to include ability	1		1											1			1
to limit access to the children's area with a check in desk. It also needs to be modernized and brightened up. Because it is partially underground it feels somewhat cave like																	
especially when approaching this area from the sanctuary. It may be worth reconfiguring the stairwell area in a way that opens it up with windows to the courtyard to make if feel more																	
inviting. i hear the carpet in the nursery is gross, but I don't know				1													
Modernize with paint, furniture, plus technology and nursery monitoring system connected to the sanctuary for parents peace of mind and security. Computerized check in for	1					1						1		1			1
move children's choir room into the 'craft' room (over the garage entrance) New paint and flooring				1													1
As I mentioned before, the Children and Youth departments should be priorities for us as a church if we hope to survive another 100 years. The Children's wing should be painted, updated			1			1								1			1
with technology, and proper check-in/check-out equipment so that families feel safe and secure leaving their children in our care and the children are in a space they enjoy. Storage (?) at																	
the end of the 1st floor leading to the stairs up to the Sanctuary level are CREEPY! They're always open, lights are always off, and it seems like the perfect place for someone to hide. We																	
need proper locks on those storage spaces so that hallway looks more like a boring hallway than something out of a horror film!! And better LIGHTING!																Page 59	

					Survey	Q16 Edu	cation bui	lding, fi	rst floor	· (Childre	en's wing)						
						Require	s Major C	apital F	unding	to Delive	r						our Mark oject(s)
	Cosmetic Improvem ents	Major Renovatio n		-	Upgrade Electrical / Plumbing	AV / Technology Security Cameras		New Playgroun d	Replace Ceiling Tiles	Landscapin	HVAC Improvements	Refurnish	Fix Roof	Improve Security	Replace Access Doors	Clean	Repaint
fine as is																	
Average Fresh paint, carpet, shelving. Add wifi to all rooms. New HVAC equip				1		1					1						1
See Answer to 15. see #14																	
Upgrade, remodel Upgrade kitchenette in children's ministry	1	1															
Clean per COVID protocol PAINT/ Clean out! Update as funds allow																1	1
COMPLETE renovation. Needs to be bright and cheery, inviting, drinkable water		1	1		1												
Totals	6	4	3	3	2	2	2	1	1	1	1	1	1	1	1	2	5

Survey Q17 Basement (Wiggins house and elevator lobby) Make Your Mark **Requires Major Capital Funding to Deliver** Day Project(s) Renovate Upgrade Elevator & Repair **ADA** Cosmetic Elevator Entrance | Add More | Electrical & Improve Outside Complete Bring Up Consideratio Replace Renovation Updates Lobby Remodel Units Plumbing Security Door to Code Flooring Clean Repaint Completely redecorate the elevator lobby, stop storing anything there. Havent seen it in awhile, just wish St. Mark had a few more serious need to spruce up 1 interior Updating with new paint better lighting in the elevator and the elevator lobby Upgrade electrical and 1 plumbing in the building; It looks and feels somewhat Elevator lobby needs flooring redo, paint as the upper floors had done in 90s or slightly after. They still look good but entrsnce is dismal. Railings on the stairwells need a regular repainting schedule Repair the area (small concrete pad) just outside the door leading from Wiggins House / basement elevator access to the parking lot. It floods whenever it rains The entrance needs complete redo Completely renovate. Looks like what it is--a parking garage with a few walls added. CLEAN, repaint, and consider redesign of access. Build out as proper apartment housing and brought up to The ADA entrance needs to be gutted and made more inviting, It is disrespectful to people with disabilities Upgrade 2 needs a lot of attention know this needs some help. 1 Maybe some LVT would help.

		S	urvey (217 Base	ement (V	Viggins 1	house a	nd elevat	or lobby	y)			
			R	Requires	Major C	apital F	unding	to Delive	er				our Mark oject(s)
	Cosmetic Updates	Renovate Elevator & Elevator Lobby	Entrance Remodel	Add More Units	Upgrade Electrical & Plumbing	Improve Security	Repair Outside Door	Complete Renovation	Bring Up to Code	ADA Consideratio n	Replace Flooring	Clean	Repaint
but could be reconfigured at ground level to make it easier to access the elevator like taking out the access door between the stairwell and Wiggins House and installing a more permanent wall and door for Wiggins House- this may be a code requirement that needs to be investigated.		1							1				
seems ok - functional welcoming and homey for our guest. Update the elevator	1	1											
create double doors between stairwell and elevator lobby, freshen up/repaint all, gut and redo kitchen I've never seen it and have		1	1					1					1
no opinion. don't know about this area Good													
Fresh paint, flooring. No comment as no knowledge of inner workings of this space.											1		1
update entryway shows wear; not a welcoming entryway Feels cold and small,	1		1										
upgrade to feel more homelike. Would any of us find the accomodations in Wiggins House satisfactory?													
All in really bad shape. Paint is off and the entire area looks scary.								1				Page 62	

		S	urvey (217 Base	ement (V	Viggins 1	house a	nd elevat	or lobby	y)			!
lean per COVID protocol 1													
		Renovate											
		Elevator &			Upgrade		Repair			ADA			
	Cosmetic	Elevator	Entrance	Add More	Electrical &	Improve	Outside	Complete	Bring Up	Consideratio	Replace		
	Updates	Lobby	Remodel	Units	Plumbing	Security	Door	Renovation	to Code	n	Flooring	Clean	Repaint
Clean per COVID protocol												1	
Extend as funds allow				1									
Totals	8	6	5	2	1	1	1	3	2	1	2	2	5

						Surve	ey Q18 A	ny other	· areas 1	10t prev	iously 1	mention	ed.							
							Requires												Make Yo Day Pr	our Mark oject(s)
	Window Repairs / Replacement	Kitchen	Plumbing	Elevator Addition / Replacement	Build Fenced Courtyard (Front)	Improve	Landscaping	Waterseal Downstai r Areas	Improve Security	HVAC	Roof	Major Facelift	Solve Water Issues	Electrical	Repair Termite	Refurnish	Space	Cosmetic Improvements	Clean	Repaint
Build a fenced courtyard on north side of front	Replacement	Opgrades	Tullionig	Replacement	1	Lighting	Lanuscaping	Alcas	Security	IIVAC	Kooi	racciiit	155005	Electrical	Damage	Returnish	Turposc	Improvements	Cican	Керапп
yard, access from hall. This will correct costly security issues and provide outside meeting spaces.					1															
Exterior lighting on front sanctuary window for evening services, better lighting in hallway running from the sanctuary to the education						1														
The paint had peeled off Interactions class wooden window frames(bare wood). I offered to prime/paint once but Deana said best to let pros do that. This is critical bldg wide since bare wood rots easily leading to costly repair.	1																			
sealing the downstairs areas where like the theatre costumes are as I've heard they often								1												
Too many church facilities look and sound like funeral homes. This can be avoided with good planning and good design.												1								
Kitchen		1																		
Repaint exterior railings and metal work on building rear on regular schedule. First impressions mean a lot.																				1
Hire a full time security officer, available during weekdays, Sunday mornings, and for special events. A churchwide intercom system for both buildings.									1											
Fix HVAC, Plumbing, Roof, Electrical, Windows. Repair any termite damage. Cosmetic improvements. Historic preservation.			1							1	1			1	1			1		
Replumbing to insure potable water throughout. See that all windows are replaced throughout as needed they are really needed.	1		1																	
Designate a permanent classroom a floral/decor studio.																	1			
The elevator should be replaced (not just renovated) Narthex and side cry room should refurnished				1												1				
and/or updated. Cry room seems to be a catchall for everything that doesn't have another																1				
The education building gutted and made new like Grace UMC did you said money was not an issue.																				
an additional elevator nearer the front of the building The whole church needs to HAVE A FACE LIFT				1								1								
like most churches do it attracts new members Kitchen fellowship hall		1										1								
I'd say the biggest concern I have is the mystery leak that nobody can really figure out how to fix. I worry this could cause structural damage so to me this is the biggest concern. Since I rolled off committees at the end of 2019 and then COVID, I don't really know if this might have already been addressed though.													1							
The state of the s	-	-	-	_	-		-	-		-								- <u> </u>	Page 64	<u> </u>

						Surve	y Q18 A	ny othei	r areas r	ot prev	iously r	nention	ed.							
							Requires	Major	Capital	Fundin	g to De	liver							Make Yo Day Pr	
	Window Repairs / Replacement	Kitchen Upgrades	Plumbing	Elevator Addition / Replacement	Build Fenced Courtyard (Front)		Landscaping	Waterseal Downstai r Areas	Improve Security	HVAC	Roof	Major Facelift	Solve Water Issues	Electrical	Repair Termite Damage	Refurnish	Space Purpose	Cosmetic Improvements	Clean	Repaint
New windows through out the physical plant that are energy efficient and secure. Update the sacristy with shelving, new counter top and cabinets and enclose the wall between the sanctuary and the sacristy. New lighting and painting in the Kilpatrick / Jones Room with a full update for meetings and Worship	1					1														
replace gym roof, repair parapet leaks between 47 & 59 buildings, get RID of, This goes for all around, infrastructure (ceiling/roof leaks, replace pipes, updated interior decorations and design)			1								1							1		
All new LED lighting - warm 3200k LED lighting - incorporate per area as construction is done with Re wire done and new ceilings as budgets allow. Love to rework Front - dress up from the entry - have a turf lawn inside ganoite post and low iron riail courtyard in front of the carpet that can be used for programs - internal and allow community engagement.						1	1													
I would like to see a separate room/area for our Blessed are the Feet ministry, where we could have a quiet and worshipful atmosphere and where there was ready access to water to wash our friends' feet. The Kitchen! Please spend a lot of attention on making the kitchen modern and new. We fee a LOT of people from that kitchen and it		1															1			
gets more use than any other part of the building. Feeding our members, staff and guests is a critical part of the soul of St. More PARKING Totals	3	3	3	2	1	3	1	1	1	1	3	2	1	1	1	1	2	2	0	1

									Survey	Q19 Pl	ease res	tate jus	t your to	p 3 prior	ities in th	e order	you wo	ould like	to see th	em comp	leted.								
											F	Requires	Major (Capital F	unding to	Delive	er												our Mark roject(s)
	Sanctuary Plaster / Paint	Plumbing / Bathrooms	Sanctuary Interior (Carpet, etc)	Gardens / Courtyard / Landscaping / Playground	Exterior	Updates for Education Bldg	Wiggins House	Improve Lighting	New Parking Walkway	Improve Wade Hall & Kitchen	Roof / Fix Leaks	Electrical	Technology / Sound System	Major Renovation of Educ Bldg	HVAC	Chapel	Gym	Elevators	Narthex	Peachtree Level Conference Rooms	Children's Wing	Repair / Replace Windows	Columbar ium	Parking	Signage	Safety	Drinking Fountains	Clean	Repaint
Sanctuary plaster/paint 2.	1	Datilloonis	eic)	1 layground	Aicas	Bidg	House	Lighting	1	Kitchen	Leaks	Electrical	System	Didg	IIVAC	Chapei	Gyiii	Elevators	Ivartitex	1	wing	Willdows	Iuiii	1 di Kilig	Signage	Salety	Toulitailis	Cicali	Керапп
Peachtree level conference																													
rooms 3. Security wall at Sound system, walkway from									1				1										1						
parking to building									1				1																
6 Repair Sanctuary, 8 Improve wade hall and kitchen. 15.	1					1				1																			
Improvements to thesecond floor																													
of the education building.								— ,	,					,															
Bridge from new parking deck to bldg.; re-build or renovate Ed.								1	1					1															
Bldg.; exterior lighting for safety																													
and to highlight bldg. at night Repairs and conservation always		1			1																		1				1		+
my goals: so exterior wood																													
prime/paint, replace bathroom toilets n urinals w low water use																			1										
units, run waterline to new																													
fountains(stop bottled water).														,															
Education building Repair water damage in	1		1			1								1															-
sanctuary. Maybe new carpet in	1		1			1																							
sanctuary. Better lighting in education building.																													
1–repair roof 2–repair sanctuary	1		1								1																		
interior plaster and paint 3-new																													
carpet and pew padding Restrooms, kitchen, and exterior		1						1		1							1												-
lighting.		-								-																			
update bathrooms and maybe electric hand dryers, better		1						1																					
lighting in bathrooms and some																													
classrooms, 1 Sanctuary interior, including	1				1												1						1						
vestibule, balcony 2 Exterior 3	1				1												1												
Gym																													
Kitchen/Wade Hall, 2. Children's Wing. 3. Sanctuary	1		1							1											1								
Santuary interior, restrooms &	1	1	1																										
plumbing, breezeway enclosure, 1. columbarium 2. Prayer				2	1	 		 									+	-	1				1	1			 	-	
garden/labyrinth outside to attract				2																			1						
guests 3. Urban garden either in																			1										
playground or elsewhere to provide fresh produce for																													
neighbors					ļ	1											-	-						-					
Upgrade the electrical and plumbing in Education Building;		1				1						1							1										
Fix the water problem above																													
stain glass windows; Give the education building a facelift																			1										
Parking, Safety, Signage																	1						1	1	1	1			
Education Building		1																1											
Plumbing/Restrooms. Elevator Lobby on ground floor. Repair																													
floor tiles in Chappel.																	1												
Fix leaks and repair sanctuary plaster. 2. Totally rehab Ed blg	1	1									1				1		1												
plumbing and HVAC 3. Rehab																			1										
the gym as indicated, particularly																													
with adequate AC Wade Hall, Parlor Restrooms,						1											 	1	+				1		†		\vdash	-	\vdash
Breezeway																							<u> </u>						
6	1		1]							1]							

									Survey	Q19 Pl	ease res	tate just	your to	p 3 prior	ities in th	e order	you wo	uld like t	o see th	em completed.								
											F	Requires 1	Major (Capital F	unding to	Delive	r											our Mark roject(s)
	Sanctua Plaster Paint	Plumbing	Sanctuary Interior (Carpet, etc)	Gardens / Courtyard / Landscaping / Playground	Exterior Areas	Updates for Education Bldg		Improve Lighting		Improve Wade Hall & Kitchen	Roof / Fix Leaks		Cechnology / Sound System	Major Renovation of Educ Bldg	HVAC	Chapel	Gym	Elevators	Narthex	Peachtree Level Conference Children's Rooms Wing	Repair / Replace Windows	Columbar ium		Signage	Safety	Drinking Fountains	Clean	Repaint
Sanctuary repair	1		1																									
landscape, courtyard, paint all of the interior				1																								1
Take an in depth look at our					1																							1
existing space and think																												
creatively about how we can																												
better utilize / make the most of it. 2. Until we can afford to do																												
more, simple cosmetic fixes																												
(lighting and painting) would																												
brighten up a lot of church space																												
that currently looks a little shabby. 3. Storage /																												
organizational solutions. We																												
never seem to have enough																												
storage space. We need to take																												
a detailed inventory and																												
ruthlessly declutter / 'Marie Kondo' Saint Mark and get rid of																												
anything we are not using .lim																												
Front landscape and lighting Second floor from garage to				2				1	1																			
 @. Second floor from garage to sanctuary 3. Gathering space 																												
after service.																												
Plumbing, Electrical, HVAC,		1										1			1													
Historic Preservation. Yes, I know that's four.																												
Kitchen, plumbing, CLEAN.		1								1																	1	+
exterior paint and spruce up,		-		1	1											1											-	
flower beds and plants/trees,				•												-												
chapel floor																												
Expand the front beds, irrigation system, and designated room for				1																								
a floral/decor studio																												
Roofs, windows and bathrooms											1										1							
Interior of Sanctuary 2.	1	1	1			1																						
Education building (2nd fl) 3. Restroom renovations																												
Leaks and plaster repair in the	1				1				1																			
sanctuary, outdoor maintenance	1																											
and parking connections to the																												
new buildings parking deck. 1) Repair the exterior and interior	1	_	1	1	1							-														-		_
issues 2)Update the sanctuary	1		1	1	1																							
3)revamp the exterior																												
Exterior lighting and green Section 1. Exterior lighting players and		1	1	1	1			1																			1	
space (including playground space an installation of an		1																										
accessible labyrinth. 2. Clean			1																									
education rooms, add																												
appropriate decor for children			1																									
and adult education and add																												
access to technology for any type of teaching. Signage and ease of	<u> </u>		<u> </u>		<u> </u>	<u></u>												<u> </u>	<u> </u>		<u></u>	<u> </u>		<u></u>	<u> </u>			
Give the church what it well																												
deserve 1) restrooms in education		+ .	+	1	1	.						-											-					-
building; 2) complete redo of the		1				1										1												
chapel; 3) updating to the rooms		1																										
and hallways in the education																												
Improved auditory system in the										·			1															
sanctuary. Restroms!		1	+	1	+	 	}	—				-					}	}	1			-	-	1	-	\vdash	 	+
3000	l	1		1	1	1	1		<u> </u>		ļ	! <u> </u> -		L			1	1	<u> </u>	+	<u>!</u>	l	L	<u> </u>	<u> </u>		L	

									Survey	Q19 Pl	ease res	tate jus	t your to	p 3 prior	ities in th	e order	you wo	ould like	to see th	nem comp	oleted.								
											F	Require	s Major (Capital F	unding to	Delive	r												our Mark roject(s)
	Sanctuary Plaster / Paint	Plumbing / Bathrooms	Sanctuary Interior (Carpet, etc)	Gardens / Courtyard / Landscaping / Playground	Exterior	Updates for Education Bldg	Wiggins House	Improve Lighting	New Parking Walkway	Improve Wade Hall & Kitchen	Roof / Fix Leaks	Electrical	Technology / Sound System	Major Renovation of Educ Bldg	HVAC	Chapel	Gym	Elevators	Narthex	Peachtree Level Conference Rooms	Children's Wing	Repair / Replace Windows	Columbar ium	Parking	Signage	Safety	Drinking Fountains	Clean	Repaint
1,2,4					1			1	1							•					Ŭ								
#1 Sanctuary roof?/whatever cause leak, repair and paint walls, #2 replace plumbing where		1									1	1																	
needed #3 update electrical system where needed																													
Needed repairs, updating flooring and decor, make it artistic and attractive																													
Sanctuary, bathrooms, drama and youth flip and renovation	1		1																										<u> </u>
Interior of sanctuary, common areas of church(bathrooms, offices, conference rooms, bridal	1		1																										
rooms, and parlor rooms, chapel The narthex, sanctuary, and educational building restrooms.			1			1													1										
18/6 (kind of the same one) / 15 / 8 - I would say these are the areas that I think new people are																													
likely to see first Exterior appearance, exterior					3																								
appearance, exterior 1, 6, 9			1		1											1													
water in sanctuary stained glass, 2. bathrooms on		1									1																		
sanctuary level 3.leaking gym roof																													
1. Infostructure repairs (water damage, water pipes, HVAC)	1	1							1																				
Sanctuary restoration Creating the Second Floor as a main entrance with																													
hospitality as the guiding 1. repair/replace roofs 2. gut	1	1									1																		
& replace bathrooms 3. fix leaks and repair plaster around	1	•																											
sanctuary windows Roof Issues, Plumbing,		1									1																		
Bathrooms More welcoming spaces for													1								1							1	1
youth/children. Improved tech throughout. Updated																													
painting/general clean-up of the building so everything looks welcoming and																													
courtyard, chapel, protection of everything else				1												1													
Education building, playground, restrooms		1		1		1																							
update bathrooms, New HVAC equip/plumbing, find water	1	1									1				1														
leak in Sanctuary & repair Restrooms, exterior, plaster in	1	1			1																								
sanctuary.											L	L				L													Ь

									Survey	Q19 Pl	ease res	tate jus	t your to	p 3 prior	ities in th	e order	you wo	uld like t	to see th	em comp	oleted.								
											F	Requires	Major (Capital F	unding to	Delive:	r												our Mark roject(s)
	Sanctuary		Sanctuary Interior	Gardens / Courtyard /		Updates for			New	Improve Wade			Technology	Major Renovation						Peachtree Level		Repair /							
	Plaster / Paint	Plumbing / Bathrooms	(Carpet, etc)	Landscaping / Playground	Exterior Areas	Education Bldg	Wiggins House	Improve Lighting	Parking Walkway	Hall & Kitchen	Roof / Fix Leaks	Electrical	/ Sound System	of Educ Bldg	HVAC	Chapel	Gym	Elevators	Narthex	Conference Rooms	Children's Wing	Replace Windows	Columbar ium	Parking	Signage	Safety	Drinking Fountains	Clean	Repaint
1) renovate Wade Hall 2)	railit	1	eic)	Flayground	Alcas	Diug	nouse	Lighting	waikway	1	Leaks	Electrical	System	Blug	1	Chapei	Gyiii	Elevators	Naturex	Kooms	wing	Willdows	Iulii	raiking	Signage	Salety	rountains	Clean	Керапп
renovate bathrooms 3)make	ľ	-								•					•														
church energy efficient																													
sanctuary, restrooms, gym roof	1	1															1												
covered walkway from the	1		1	1					1																				
new parking deck to the																													
church; 2. new carpet/plaster in																													
the vestibule and sanctuary; 3.																													
new plantings																													
Education wing (all floors),	1	1				1	1																						
Bathrooms, Wiggins House																													
1, Restrooms in educational	1	1															1				1								
building renovated 2.]		
Kitchenette in children's																													
ministry upgraded 3. State of																													
the art gymnasium																													
Number 12, 3, and 1		1		1	1																								
Blow out main level - update				1						1				1															
entire floor form parking to																													
chapel to front door -																													
willinclude new restrooms;																													
Compelete Sancutary updates,																													
fix water intrusion any repairs,																													
RE-work wade hall and inner																													
courtyard (include back walk																													
or I enclosed connections - and																													
flow buy kids improvements																													
(all done whole general funds																													
cover Music and dram yearly																													
funds needed - hole special																													
funraisers fro music and kids																													
to ensure major fundin goes to																													
the most neglected areas.																													
GA																		-											
Roof repair, restroom	1	1									1				1														
renovations, HVAC	ľ	•									•				•														
replacement																													
1, 13, 8					1					1							1												
Sanctuary wall, bridge to new	1			1					1	•																			
parking facility, and	•			•					•																				
Playground.																													
Kitchen and maintain the look										1																			
and feel of the main building.										•																			
Stop water damage. Breezeway									1		1						1	-											
Reno and best use of gym									-		l ⁻						ľ]		
an out door pavilion	+			1	 	1	-				-					1	 	 	}		-		 	1	1		+ -		1
More parking?				•																				1					
Childrens wing	+				 	1	-				-					1	 	 	}		1		 	l [*]	1		+ -		1
Total	22	26	13	16	14	8	1	6	10	8	10	3	3	3	5	4	6	1	1	1	4	1	1	2	1	1	1	3	3
2 0 000		20	10	10		U		v	10	U	10	J	ı J			7	·	-			-								